



Aviation Investigation Final Report

Location: ANCHORAGE, Alaska Accident Number: ANC84LA186

Date & Time: September 19, 1984, 13:58 Local Registration: N9143L

Aircraft: CHAMPION 7KCAB Aircraft Damage: Substantial

Defining Event: 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE FLOAT EQUIPPED ACFT CRASHED WHILE MANEUVERING NEAR A SMALL LAKE. THE PLT STATED THAT WHILE AT 1000 FT AGL THE ENG 'COUGHED A FEW TIMES AND DIED'. THE PLT TOLD THE RESCUE CREW THAT HIS ENG ICED-UP WHILE WAS AT LOW ALT. THE PASSENGER STATED THAT THE ACFT STALLED DURING A LOW LEVEL TURN. CONFLICTING STATEMENTS THROUGHOUT THE INVESTIGATION PROVIDED CONTRADICTORY INFORMATION CONCERNING THE OPERATION OF THIS FLT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: MANEUVERING

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: LOSS OF CONTROL - IN FLIGHT Phase of Operation: DESCENT - EMERGENCY

Findings

2. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

3. STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 6 ANC84LA186

Factual Information

Pilot Information

Certificate:	Commercial	Age:	38,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Expired	Last FAA Medical Exam:	November 18, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	2274 hours (Total, all aircraft), 200 hours (Total, this make and model), 1965 hours (Pilot In Command, all aircraft), 920 hours (Last 90 days, all aircraft), 11 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC84LA186

Aircraft and Owner/Operator Information

Aircraft Make:	CHAMPION	Registration:	N9143L
Model/Series:	7KCAB 7KCAB	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Aerobatic; Normal	Serial Number:	288-71
Landing Gear Type:	Float	Seats:	2
Date/Type of Last Inspection:	March 10, 1984 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	50 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	900 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	IO-320-E2A
Registered Owner:	JAMES HARVARD ROOKS	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	10°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	ANCHORAGE , AK (AK83)	Type of Flight Plan Filed:	None
Destination:	ANCHORAGE , AK (AK83)	Type of Clearance:	None
Departure Time:	11:30 Local	Type of Airspace:	Class G

Page 4 of 6 ANC84LA186

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	

Page 5 of 6 ANC84LA186

Administrative Information

Investigator In Charge (IIC):	Stella, Marc
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4379

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC84LA186