



Aviation Investigation Final Report

Location: SOLDOTNA, Alaska Accident Number: ANC86LA048

Date & Time: April 24, 1986, 18:15 Local Registration: N78564

Aircraft: PIPER PA-12 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT STATED THAT THE AIRCRAFT IS NOT EQUIPPED WITH A HEADER TANK ON THE FUEL SYSTEM. THE ENGINE WAS STARVED OF FUEL WHEN IN A SHALLOW DIVE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: LANDING

Findings

1. (C) FUEL SYSTEM, LINE - STARVATION

2. (C) FUEL SUPPLY - DELAYED - PILOT IN COMMAND

3. (C) FLIGHT MANUALS - DISREGARDED - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: LANDING

ANC86LA048 Page 2 of 5

Factual Information

Pilot Information

Certificate:	Commercial	Age:	45,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Expired	Last FAA Medical Exam:	April 27, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1236 hours (Total, all aircraft), 575 hours (Total, this make and model), 1112 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N78564
Model/Series:	PA-12 PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	123939
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 23, 1977 Annual	Certified Max Gross Wt.:	1550 lbs
Time Since Last Inspection:	665 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2234 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-320
Registered Owner:	GERALD E. JONES	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC86LA048

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
	Distance from Accident Site:	
	Direction from Accident Site:	
Clear	Visibility	50 miles
None	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	/
0°	Turbulence Severity Forecast/Actual:	/
29 inches Hg	Temperature/Dew Point:	4°C / -7°C
No Obscuration; No Precipita	ation	
	Type of Flight Plan Filed:	None
	Type of Clearance:	None
00:00 Local	Type of Airspace:	Class G
	Clear None / 0° 29 inches Hg No Obscuration; No Precipita	Distance from Accident Site: Direction from Accident Site: Visibility None Visibility (RVR): / Turbulence Type Forecast/Actual: 0° Turbulence Severity Forecast/Actual: 29 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Type of Flight Plan Filed: Type of Clearance:

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	60.320148,-150.789566(est)

Page 4 of 5 ANC86LA048

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4654

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC86LA048