



Aviation Investigation Final Report

Location: KUSKATAN RIVER, Alaska Accident Number: ANC86LA123

Date & Time: August 6, 1986, 22:00 Local Registration: N1163E

Aircraft: Champion 7GCBC Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING THE TAKEOFF ROLL ON A RIVER GRAVEL BAR, THE PILOT LOST DIRECTIONAL CONTROL OF THE AIRCRAFT CAUSING THE AIRCRAFT TO NOSE OVER ON ITS BACK.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

- 1. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA INATTENTIVE PILOT IN COMMAND
- 2. (F) IMPROPER USE OF PROCEDURE PILOT IN COMMAND
- 3. (C) AIRCRAFT HANDLING NOT MAINTAINED PILOT IN COMMAND
- 4. (C) DIRECTIONAL CONTROL NOT ATTAINED PILOT IN COMMAND

Occurrence #2: NOSE OVER

Phase of Operation: TAKEOFF - ROLL/RUN

Factual Information

Pilot Information

Certificate:	Private	Age:	32,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 6, 1985
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	473 hours (Total, all aircraft), 448 hours (Total, this make and model), 408 hours (Pilot In Command, all aircraft), 66 hours (Last 90 days, all aircraft), 33 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Champion	Registration:	N1163E
Model/Series:	7GCBC 7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	98777
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	May 1, 1986 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	84 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2017 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-320
Registered Owner:	DALE D. KISSEE	Rated Power:	150 Horsepower
Operator:	DONALD J. KLEVEN	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 ANC86LA123

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 5000 ft AGL	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 3 of 4 ANC86LA123

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4712

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ANC86LA123