

Aviation Investigation Final Report

Location:	FAIRBANKS, Alaska		Accident Number:	ANC88LA043
Date & Time:	April 17, 1988, 13:30	Local	Registration:	N5060R
Aircraft:	CESSNA	185	Aircraft Damage:	Substantial
Defining Event:			Injuries:	3 None
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

THE PILOT STATED THAT HE MADE A HARD LANDING AND AT THAT TIME HE LOST DIRECTIONAL CONTROL OF THE AIRCRAFT. THE PLT STATED THAT THE ACFT BOUNCED AND WHEN HE TRIED TO CORRECT THE BOUNCE THE ACFT YAWED LEFT. THE RT MAIN GEAR COLLAPSED AND THE ACFT GROUNDLOOPED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
1. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings 2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial	Age:	24,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 10, 1987
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	276 hours (Total, all aircraft), 13 hours (Total, this make and model), 254 hours (Pilot In Command, all aircraft), 13 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N5060R
Model/Series:	185 185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18502992
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1908 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D
Registered Owner:	ROBERT W WINDSOR	Rated Power:	300 Horsepower
Operator:	WINDSOR, ROBERT W.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	20000 ft AGL	Visibility	60 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	11°C / -12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	CENTRAL , AK (CEM)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:45 Local	Type of Airspace:	Class D

Airport Information

Airport:	FAIRBANKS FAI	Runway Surface Type:	Asphalt
Airport Elevation:	434 ft msl	Runway Surface Condition:	Dry
Runway Used:	19R	IFR Approach:	None
Runway Length/Width:	10300 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	64.809181,-147.720321(est)

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	
Original Publish Date:	April 25, 1989
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4997

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.