



Aviation Investigation Final Report

Location: FAIRBANKS, Alaska Accident Number: ANC88LA050

Date & Time: April 24, 1988, 20:45 Local Registration: N91290

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT RETURNED TO FAIRBANKS INT'L AIRPORT FROM AN INTENDED CROSS-COUNTRY FLIGHT DUE TO DETERIORATING WEATHER. DURING THE FLIGHT THE AIRPLANE FELT OUT OF TRIM, AND SHE ELECTED TO LAND ON THE LONGEST RUNWAY AVAILABLE (10,300). DURING THE LANDING ROLL SHE LOST DIRECTIONAL CONTROL AND GROUND-LOOPED TO THE RIGHT. SHE SAID SHE HAD NOT FLOWN FOR AT LEAST 90 DAYS PRIOR TO THE ACCIDENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

- 2. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT PILOT IN COMMAND
- 3. (F) LACK OF RECENT EXPERIENCE IN TYPE OF AIRCRAFT PILOT IN COMMAND

Occurrence #2: DRAGGED WING,ROTOR,POD,FLOAT OR TAIL/SKID Phase of Operation: LANDING - ROLL

Page 2 of 5 ANC88LA050

Factual Information

Pilot Information

Certificate:	Private	Age:	58,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 18, 1988
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	862 hours (Total, all aircraft), 4 hours (Total, this make and model), 795 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N91290
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052030
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 28, 1988 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	855 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-470
Registered Owner:	SCHIKORA, MARY ANN	Rated Power:	230 Horsepower
Operator:	SCHIKORA, MARY ANN	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 ANC88LA050

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FAI ,434 ft msl	Distance from Accident Site:	
Observation Time:	20:51 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 8000 ft AGL	Visibility	60 miles
Lowest Ceiling:	Broken / 12000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	12°C / -6°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	None
Departure Time:	17:20 Local	Type of Airspace:	Class D

Airport Information

Airport:	FAIRBANK INT'L FAI	Runway Surface Type:	Asphalt
Airport Elevation:	434 ft msl	Runway Surface Condition:	Dry
Runway Used:	19R	IFR Approach:	None
Runway Length/Width:	10300 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	64.80928,-147.719558(est)

Page 4 of 5 ANC88LA050

Administrative Information

Investigator In Charge (IIC): La belle, James

Additional Participating
Persons:

Original Publish Date: April 25, 1989

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=5002

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC88LA050