



Aviation Investigation Final Report

Location: DILLINGHAM, Alaska Accident Number: ANC89LA112

Date & Time: June 30, 1989, 18:05 Local Registration: N6305E

Aircraft: CESSNA 185F Aircraft Damage: Substantial

Defining Event: 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT OF A FLOAT PLANE RPRTD THAT HE MADE A LOW PASS OVER A BEACH AT 100' AGL TO CHECK FOR A FUTURE WHEEL LANDING AREA. REPORTEDLY, THE ACFT ENCOUNTERED A DOWNDRAFT DRG THE LOW PASS THAT EXCEEDED ITS CLIMB CAPABILITY. SUBSEQUENTLY, IT IMPACTED ON THE BEACH AT AN AIRSPEED OF ABOUT 90 KTS & NOSED OVER. THE FRONT SEAT OCCUPANTS OF THE ACFT BELIEVED THAT USE OF THE SHOULDER HARNESSES PROBABLY SAVED THEIR LIVES.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER PLANNING/DECISION BY THE PILOT & A STRONG DOWNDRAFT.

Findings

Occurrence #1: ALTITUDE DEVIATION, UNCONTROLLED

Phase of Operation: MANEUVERING

Findings

1. LOW PASS - PERFORMED - PILOT IN COMMAND

- 2. (C) WEATHER CONDITION DOWNDRAFT
- 3. (C) IN-FLIGHT PLANNING/DECISION IMPROPER PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING

Page 2 of 6 ANC89LA112

Factual Information

Pilot Information

| Certificate: | Commercial | Age: | 50.Male |
|---------------------------|---|-----------------------------------|-------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea | Seat Occupied: | Unknown |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medicalno waivers/lim. | Last FAA Medical Exam: | May 1, 1989 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 4500 hours (Total, all aircraft), 4200 hours (Total, this make and model), 4500 hours (Pilot In Command, all aircraft), 220 hours (Last 90 days, all aircraft), 130 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft) | | |

Page 3 of 6 ANC89LA112

Aircraft and Owner/Operator Information

| Aircraft Make: | CESSNA | Registration: | N6305E |
|-------------------------------|--|-----------------------------------|-----------------|
| Model/Series: | 185F 185F | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 1850422 |
| Landing Gear Type: | Float | Seats: | 4 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 3362 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | CONTINENTAL |
| ELT: | Installed, activated, aided in locating accident | Engine Model/Series: | IO-520-D |
| Registered Owner: | LEE A HOTCHKISS | Rated Power: | 300 Horsepower |
| Operator: | HOTCHKISS, LEE A. | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| meteororogioai informati | <u> </u> | | |
|----------------------------------|------------------------------|--------------------------------------|--------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | | Distance from Accident Site: | |
| Observation Time: | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Scattered / 5000 ft AGL | Visibility | 60 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 15 knots / 20 knots | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 300° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 21°C / -18°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | | Type of Flight Plan Filed: | VFR |
| Destination: | DILLINGHAM , AK (DLG) | Type of Clearance: | None |
| Departure Time: | 18:00 Local | Type of Airspace: | |

Page 4 of 6 ANC89LA112

Airport Information

| Airport: | | Runway Surface Type: | |
|----------------------|---|---------------------------|------|
| Airport Elevation: | | Runway Surface Condition: | |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | None |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|----------------------------|
| Passenger Injuries: | 3 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 4 None | Latitude, Longitude: | 58.820316,-157.860244(est) |

Page 5 of 6 ANC89LA112

Administrative Information

Investigation Docket:

Investigator In Charge (IIC): Daw, Roy

Additional Participating
Persons:

Original Publish Date: April 19, 1990

Last Revision Date:
Investigation Class: Class
Note:

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

https://data.ntsb.gov/Docket?ProjectID=5215

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC89LA112