



Aviation Investigation Final Report

Location: IGIUGIG, Alaska Accident Number: ANC90LA149

Date & Time: August 17, 1990, 09:30 Local Registration: N3455A

Aircraft: PIPER PA-22 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

AFTER TOUCHDOWN ON THE GRAVEL BAR, THE PILOT LOST DIRECTIONAL CONTROL OF THE AIRPLANE. THE AIRPLANE THEN GROUND LOOPED TO THE RIGHT AND NOSED OVER ON ITS BACK. THE AIRPLANE WAS SUBSTANTIALLY DAMAGED. THE PILOT AND PASSENGER WERE NOT INJURED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL ON LANDING. CONTRIBUTING TO THE ACCIDENT WAS UNSUITABLE TERRAIN SELECTED BY THE PILOT FOR LANDING.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - ROUGH/UNEVEN

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Occurrence #3: NOSE OVER Phase of Operation: LANDING - ROLL

Page 2 of 6 ANC90LA149

Factual Information

Pilot Information

Certificate:	Private	Age:	52,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 4, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	214 hours (Total, all aircraft), 97 hours (Total, this make and model), 200 hours (Pilot In Command, all aircraft), 14 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC90LA149

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N3455A
Model/Series:	PA-22 PA-22	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1732
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	March 21, 1990 Annual	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:	15 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2007 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	0-320
Registered Owner:		Rated Power:	150 Horsepower
Operator:	ROBERT BUMBAUGH	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Assidant Citae	Viewel (VMC)	Condition of Limbs	Davi
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	2 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	13°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	None
Departure Time:	09:30 Local	Type of Airspace:	Class G

Page 4 of 6 ANC90LA149

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	58.749889,-156.54013(est)

Page 5 of 6 ANC90LA149

Administrative Information

Investigator In Charge (IIC): Michelangelo, James

Additional Participating Persons:

Original Publish Date: September 15, 1992

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=5432

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC90LA149