



Aviation Investigation Final Report

Location:	KODIAK, Alaska	Accident Number:	ANC90LA154
Date & Time:	August 24, 1990, 13:30 Local	Registration:	N8827D
Aircraft:	PIPER PA-22-150	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

AFTER TOUCHDOWN ON THE WATER, THE PILOT LOST DIRECTIONAL CONTROL OF THE AIRPLANE. THE AIRPLANE SUDDENLY WHIPPED TO THE LEFT AND ROLLED OVER AND SANK. THE AIRPLANE WAS SUBSTANTIALLY DAMAGED. TE PILOT AND PASSENGER WERE NOT INJURED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL AND FAILURE TO MAINTAIN AIRPLANE CONTROL ON LANDING.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

1. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND
 2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
-

Occurrence #2: NOSE OVER
Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Private	Age:	31, Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim	Last FAA Medical Exam:	April 24, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	147 hours (Total, all aircraft), 10 hours (Total, this make and model), 91 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N8827D
Model/Series:	PA-22-150 PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	225996
Landing Gear Type:	Float	Seats:	2
Date/Type of Last Inspection:	August 22, 1990 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:	2 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2589 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-320
Registered Owner:	UNKNOWN	Rated Power:	150 Horsepower
Operator:	HANSEN, ARNOLD T. JR.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 10000 ft AGL	Visibility	100 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	16°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:44 Local	Type of Airspace:	Class G

Airport Information

Airport:	LILYLAKE 923	Runway Surface Type:	Water
Airport Elevation:	130 ft msl	Runway Surface Condition:	Water-calm
Runway Used:	2	IFR Approach:	None
Runway Length/Width:	2100 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	57.789249,-152.399856(est)

Administrative Information

Investigator In Charge (IIC): Michelangelo, James

Additional Participating Persons: ;

Original Publish Date: September 15, 1992

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.ntsb.gov/Docket?ProjectID=5437>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).