

Aviation Investigation Final Report

Location:	PILOT POINT, Alaska	3	Accident Number:	ANC91LA073
Date & Time:	June 12, 1991, 22:30	Local	Registration:	N420SB
Aircraft:	CESSNA	180	Aircraft Damage:	Substantial
Defining Event:			Injuries:	3 None
Flight Conducted Under:	Part 91: General avia	ition - Personal		

Analysis

WHILE IN CRUISE FLIGHT, THE ENGINE QUIT. AFTER AN EMERGENCY LANDING ON THE TUNDRA, THE AIRPLANE NOSED OVER ON ITS BACK. EXAMINATION OF THE AIRPLANE SHOWED THAT BOTH FUEL TANKS WERE EMPTY, AND THE PILOT STATED HE JUST RAN OUT OF FUEL.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FUEL EXHAUSTION, DUE TO THE PILOT'S INADEQUATE PREFLIGHT. CONTRIBUTING TO THE ACCIDENT WAS THE SOFT AND ROUGH TERRAIN.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF Phase of Operation: CRUISE

Findings 1. (C) FUEL SYSTEM - EXHAUSTION 2. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY Occurrence #3: NOSE OVER Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Commercial	Age:	40,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 10, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3613 hours (Total, all aircraft), 1438 hours (Total, this make and model), 3278 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N420SB
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052313
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	June 10, 1991 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	7 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3489 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	0-470
Registered Owner:		Rated Power:	230 Horsepower
Operator:	BOBBY GRAHAM	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	98 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	25 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	13°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	GERTRUDE CREEK , AK (NONE)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	20:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	57.499473,-157.280639(est)

Administrative Information

Investigator In Charge (IIC):	Michelangelo, James
Additional Participating Persons:	FSDO-03; ANCHORAGE , AK
Original Publish Date:	March 31, 1993
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=5557

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.