



Aviation Investigation Final Report

Location: WEST POINT, Virginia Accident Number: ATL83LA251

Date & Time: July 2, 1983, 08:00 Local Registration: N5920M

Aircraft: CESSNA 310 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT STATED THAT HE WAS PRACTICING SINGLE ENGINE PROCEDURES AND LANDINGS. ON HIS FOURTH LANDING TO A FULL STOP HE LANDED GEAR UP. HE SAID HE JUST FORGOT TO PUT THE GEAR DOWN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: COMPLETE GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) CHECKLIST - NOT USED - PILOT IN COMMAND

2. (C) GEAR EXTENSION - NOT PERFORMED - PILOT IN COMMAND

3. (F) WHEELS UP LANDING - INADVERTENT - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial	Age:	20,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	July 20, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	826 hours (Total, all aircraft), 77 hours (Total, this make and model), 712 hours (Pilot In Command, all aircraft), 217 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N5920M
Model/Series:	310 310	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	310P022
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	July 1, 1983 Annual	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:	0 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	2533 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-470-VO
Registered Owner:	JAMES MILLER	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 ATL83LA251

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	2 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	07:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	WEST POINT MUNI W97	Runway Surface Type:	Asphalt
Airport Elevation:	25 ft msl	Runway Surface Condition:	Dry
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	3750 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.590637,-76.459411(est)

Page 3 of 4 ATL83LA251

Administrative Information

Investigator In Charge (IIC):	Henderson, Dennis
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=6109

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ATL83LA251