

Aviation Investigation Final Report

PIPELINE

Location:	Winder, Georgia	Accident Number:	NYC08CA108
Date & Time:	February 19, 2008, 17:00 Local	Registration:	N47EA
Aircraft:	Aviat A-1B	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

According to the pilot of an Avitat A-1B, while departing from runway 23, "a gust of wind caused a ground loop type maneuver." He applied additional engine power in an attempt to straighten out the airplane, but "the wind overpowered me and I rolled off into the woods." He also stated that the landing gear was bent due to the inadvertent side load; causing the wing and propeller to strike the ground. The tail section and fuselage were bent as the airplane preceded tail first into the trees. The pilot did not report any mechanical malfunctions of the airplane prior to the accident. The reported wind at the airport, about the time of the accident, was from 290 degrees at 14 knots, gusting to 24 knots.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during the takeoff roll. Contributing to the accident was the gusty crosswind condition.

Findings

Environmental issues	Gusts - Not specified	
Aircraft	Directional control - Not attained/maintained	
Environmental issues	Crosswind - Not specified	
Personnel issues	Incorrect action performance - Pilot	
Environmental issues	Tree(s) - Not specified	

Factual Information

History of Flight

Takeoff	Loss of control on ground (Defining event)
Takeoff	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	40,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3	Last FAA Medical Exam:	December 1, 2007
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1100 hours (Total, all aircraft), 50 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Aviat	Registration:	N47EA
Model/Series:	A-1B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2359
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	O-360
Registered Owner:	Brad Mercer	Rated Power:	
Operator:	Brad Mercer	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Observation Facility, Elevation:	KWDR,934 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	17:01 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	14 knots / 24 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.13 inches Hg	Temperature/Dew Point:	12°C / -3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Winder, GA (KWDR)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	Unknown
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Winder-Barrow Airport WDR	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Unknown
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	3610 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.989883,-83.720336(est)

Administrative Information

Investigator In Charge (IIC):	Etcher, Shawn
Additional Participating Persons:	Steve Newcomer; FAA/FSDO; Atlanta, GA
Original Publish Date:	April 30, 2008
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67562

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.