



Aviation Investigation Final Report

Location: Lincoln, Nebraska Accident Number: DFW08CA120

Date & Time: April 27, 2008, 13:00 Local Registration: N1020Q

Aircraft: Hughes 269A Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The commercial rated pilot was practicing a steep approach in a single-engine helicopter, when she flared too low to the ground and the tail rotor struck the ground. Subsequently, the tail rotor drive shaft failed and the pilot was unable to maintain control of the helicopter. The rear portion of the right skid contacted the ground and the helicopter rolled over on to its side. Examination of the helicopter revealed it sustained substantial damage to the mast, tail boom, and the right skid was torn from the fuselage.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to properly execute a steep approach, which resulted in a tail strike and a loss of control.

Findings

Personnel issues Aircraft control - Pilot

Factual Information

History of Flight

Maneuvering Collision with terr/obj (non-CFIT) (Defining event)

Pilot Information

Certificate:	Commercial	Age:	35,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2	Last FAA Medical Exam:	March 1, 2008
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1672 hours (Total, all aircraft), 23 hours (Total, this make and model), 30 hours (Last 90 days, all aircraft), 19 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hughes	Registration:	N1020Q
Model/Series:	269A	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	115-0426
Landing Gear Type:	Skid	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	10-360
Registered Owner:	Advanced Air Incorporated	Rated Power:	
Operator:	Chandra Clanton	Operating Certificate(s) Held:	None

Page 2 of 4 DFW08CA120

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Lincoln, NE (NONE)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	1 None	Latitude, Longitude:	40.850555,-96.755554

Page 3 of 4 DFW08CA120

Administrative Information

Investigator In Charge (IIC):	Yeager, Leah
Additional Participating Persons:	Robert Wiley; FAA FSDO; Lincoln, NE
Original Publish Date:	May 28, 2008
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=67896

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DFW08CA120