

# **Aviation Investigation Final Report**

Location:	MARYSVILLE, Ohio		Accident Number:	ATL86FEK07
Date & Time:	August 30, 1986, 18	3:00 Local	Registration:	N3678Q
Aircraft:	BEECH	A23A	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional			

#### **Analysis**

THE ACFT PORPOISED AND NOSED DOWN DURING LANDING. THE PLT REPORTED THAT ON THE SECOND LANDING ATTEMPT, THE ACFT BOUNCED AND SHE FAILED TO APPLY POWER SOON ENOUGH TO EFFECT A RECOVERY.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) FLARE - IMPROPER - PILOT IN COMMAND

2. (C) RECOVERY FROM BOUNCED LANDING - DELAYED - PILOT IN COMMAND

## **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	37,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 26, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	51 hours (Total, all aircraft), 51 hours (Total, this make and model), 12 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

#### Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N3678Q
Model/Series:	A23A A23A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	M-1050
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	August 30, 1985 Annual	Certified Max Gross Wt.:	2350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1882 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	IO-346-A
Registered Owner:		Rated Power:	165 Horsepower
Operator:	HENRY BURK	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

#### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	21°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	ZANESVILLE , OH (ZZV )	Type of Flight Plan Filed:	VFR
Destination:	MARYSVILLE , OH (I78 )	Type of Clearance:	VFR
Departure Time:	00:00 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	UNION COUNTY 178	Runway Surface Type:	Asphalt
Airport Elevation:	1017 ft msl	Runway Surface Condition:	Dry
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	4220 ft / 75 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.229621,-83.37046(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Young, Burnham
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=6986

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.