

Aviation Investigation Final Report

RAIL ROAD

PIPELINE

Location:	BETHEL, Pennsylva	ania	Accident Number:	NYC83FHA01
Date & Time:	November 16, 1982	2, 10:45 Local	Registration:	N2581R
Aircraft:	PIPER	PA-28-180	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Serious
Flight Conducted Under:	Part 91: General av	iation - Personal		

Analysis

WITNESSES STATED THE AIRCRAFT MADE SEVERAL LOW LEVEL PASSES OVER A FARM HOUSE INCLUDING FLYING UNDER POWERLINES BEFORE COLLIDING WITH A TREE. THE PILOT, WHO WAS SERIOUSLY INJURED COULD NOT REMEMBER THE CIRCUMSTANCES LEADING TO THE ACCIDENT. EXAMINATION OF THE AIRCRAFT ENGINE DID NOT REVEAL DESCREPANCIES AND INDICATED THAT THE ENGINE APPEARED CAPABLE OF OPERATING NORMALLY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: MANEUVERING

Findings

- 1. (C) JUDGMENT POOR PILOT IN COMMAND
- 2. (C) BUZZING PERFORMED PILOT IN COMMAND

4. (C) PROPER ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

^{3.} OBJECT - TREE(S)

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	40,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	November 11, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1595 hours (Total, all aircraft), 1588 hours (Total, this make and model), 1406 hours (Pilot In Command, all aircraft), 29 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N2581R
Model/Series:	PA-28-180 PA-28-180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	28-5681
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2175 lbs
Time Since Last Inspection:	8 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	828 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-360-A4A
Registered Owner:	JAMES V. ROY,INC.	Rated Power:	180 Horsepower
Operator:	JAMES V. ROY,INC.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
		-	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	LEBANON VALLEY , PA	Type of Flight Plan Filed:	None
Destination:	SOMERSET , NJ	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	November 16, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=69938

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.