



Aviation Investigation Final Report

Location: DOUGLAS, Wyoming Accident Number: DEN82FTC05

Date & Time: June 11, 1982, 09:30 Local Registration: N73221

Aircraft: BELL 47G-3B Aircraft Damage: Substantial

Defining Event: 2 Minor

Flight Conducted Under: Part 137: Agricultural

Analysis

THE PILOT REPORTED THAT HE MADE A NORMAL APPROACH TO THE LANDING SITE NEAR HIS LOADING DOCK. WHEN HE TOUCHED DOWN, THE HELICOPTER AS ON A SLOPE, SO HE PICKED THE CRAFT BACK UP TO A HOVER. REPORTEDLY, HE WAS MOVING THE HELICOPTER ABOUT 4 FT FORWARD TO A MORE LEVEL POSITION WHEN A GUST OF WIND FROM THE RIGHT DRIFTED THE CRAFT TO THE LEFT. SUBSEQUENTLY, THE MAIN ROTOR BLADES STRUCK THE TOP OF THE LOADING DOCK. THE PILOT REPORTED THAT THE WIND WAS VARIABLE BETWEEN 270 AND 360 DEGREES AT 5, GUSTING 10 KTS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: LANDING

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) WEATHER CONDITION - UNFAVORABLE WIND

3. (C) COMPENSATION FOR WIND CONDITIONS - IMPROPER - PILOT IN COMMAND

Page 2 of 5 DEN82FTC05

Factual Information

Pilot Information

Certificate:	Commercial	Age:	36,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 2, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	7190 hours (Total, all aircraft), 4700 hours (Total, this make and model), 24 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELL	Registration:	N73221
Model/Series:	47G-3B 47G-3B	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	2757
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2950 lbs
Time Since Last Inspection:	22 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5407 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	TVO 435
Registered Owner:	DARE R. WILLIAMS	Rated Power:	280 Horsepower
Operator:	DARE R. WILLIAMS	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN82FTC05

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	60°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	DOUGLAS , WY	Type of Flight Plan Filed:	None
Destination:	DOUGLAS , WY	Type of Clearance:	None
Departure Time:	09:00 Local	Type of Airspace:	

Airport Information

Airport:	FIELD STRIP	Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	1 Minor	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	

Page 4 of 5 DEN82FTC05

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: June 11, 1983

Last Revision Date:

Investigation Class: Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=70496

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN82FTC05