



Aviation Investigation Final Report

Location: FRESNO, California Accident Number: LAX82DA333

Date & Time: September 3, 1982, 19:30 Local Registration: N6212V

Aircraft: BEECH 95-A55 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Ferry

Analysis

THE AIRCRAFT WAS BEING FERRIED TO THE NEW OWNER WHEN IT MADE A HARD LANDING AND COLLAPSED THE LANDING GEAR. THE NEW OWNER COULD NOT BE LOCATED AND THE BROKER WAS UNABLE TO FURNISH ANY INFORMATION AS TO THE IDENTITY OF THE PILOT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) FLARE - IMPROPER - PILOT IN COMMAND

2. (C) FLIGHT CONTROLS - IMPROPER USE OF - PILOT IN COMMAND

Occurrence #2: COMPLETE GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. (F) LANDING GEAR - OVERLOAD

Page 2 of 5 LAX82DA333

Factual Information

Pilot Information

Certificate:		Age:	Male
Airplane Rating(s):		Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N6212V
Model/Series:	95-A55 95-A55	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	TC-327
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	4880 lbs
Time Since Last Inspection:	0 Hrs	Engines:	2 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	10-470-L
Registered Owner:	DONALD C. HARPER	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX82DA333

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/dark
Observation Facility, Elevation:	FAT	Distance from Accident Site:	6 Nautical Miles
Observation Time:	18:51 Local	Direction from Accident Site:	40°
Lowest Cloud Condition:	Clear	Visibility	30 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	93°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	MADERA , CA (MAE)	Type of Flight Plan Filed:	None
Destination:	RIVER SIDE , CA (RAL)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	FRESNO CHANDLER DOWNTOWN FCH	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	30	IFR Approach:	
Runway Length/Width:	3441 ft / 75 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.750522,-119.669281(est)

Page 4 of 5 LAX82DA333

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: September 3, 1983

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=70761

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX82DA333