



Aviation Investigation Final Report

Location: PHILIP, South Dakota Accident Number: DEN82DA180

Date & Time: August 31, 1982, 15:30 Local Registration: CFHYE

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation

Analysis

PILOT LOST DIRECTIONAL CONTROL DURING LANDING AND GROUNDLOOPED. PILOT STATED HE ENCOUNTERED A STRONG CROSSWIND GUST FROMA THUNDERSTORM IN THE AREA.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) WEATHER CONDITION - GUSTS

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

4. GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	42,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	760 hours (Total, all aircraft), 300 hours (Total, this make and model), 45 hours (Last 90 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	CFHYE
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	0-470
Registered Owner:	BILL EAST	Rated Power:	230 Horsepower
Operator:	BILL EAST	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 DEN82DA180

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	20 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	45°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	HASTINGS , NE (C)	Type of Flight Plan Filed:	None
Destination:	(C)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	PHILIP PNP	Runway Surface Type:	Grass/turf
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	
Runway Length/Width:	3600 ft / 150 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	44.039333,-101.6604(est)

Page 3 of 4 DEN82DA180

Administrative Information

Investigation Docket:

we adjudicate appeals of civil penalty actions taken by the FAA.

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: August 31, 1983

Last Revision Date:
Investigation Class: Class

Note:

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions

involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and

https://data.ntsb.gov/Docket?ProjectID=72208

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DEN82DA180