



Aviation Investigation Final Report

Location: PINEVILLE, Louisiana Accident Number: FTW83LA006

Date & Time: October 3, 1982, 16:28 Local Registration: N707PC

Aircraft: CESSNA 180K II Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING LANDING THE ACFT VEERED RIGHT & THE LEFT MAIN GEAR COLLAPSED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

2. GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

3. LANDING GEAR, MAIN GEAR - OVERLOAD

Factual Information

Pilot Information

Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 3, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	100 hours (Total, all aircraft), 27 hours (Total, this make and model), 50 hours (Pilot In Command, all aircraft), 49 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N707PC
Model/Series:	180K II 180K II	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	18053157
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	480 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	O-470-U
Registered Owner:	ERNEST E. PADGETT, JR.	Rated Power:	230 Horsepower
Operator:	ERNEST E. PADGETT, JR.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 FTW83LA006

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ESF	Distance from Accident Site:	
Observation Time:	16:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4500 ft AGL	Visibility	5 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	86°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	OPELOUSAS , LA (OPL)	Type of Flight Plan Filed:	None
Destination:	ETHEL , AR	Type of Clearance:	
Departure Time:	15:45 Local	Type of Airspace:	

Airport Information

Airport:	ESLER FIELD ESF	Runway Surface Type:	Concrete
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	32	IFR Approach:	
Runway Length/Width:	5200 ft / 150 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	31.329063,-92.409858(est)

Page 3 of 4 FTW83LA006

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date:
October 3, 1983

Last Revision Date:
Investigation Class:

Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=72237

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 FTW83LA006