



Aviation Investigation Final Report

Location: PLACIDA, Florida Accident Number: MIA82DA083

Date & Time: March 24, 1982, 16:00 Local Registration: N8043Y

Aircraft: PIPER PA-30 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE PILOT STATED THAT DURING THE BEGINNING OF THE LANDING ROLL THE RIGHT MAIN AND NOSE LANDING GEARS COLLAPSED. EXAMINATION REVEALED THAT THE RETRACTION TORQUE TUBE ARM FITTING, PIPER P/N 21012-03, WHICH LINKS THE RIGHT MAIN AND NOSE GEAR TO THE RETRACTION SYSTEM, FAILED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR, NORMAL RETRACTION/EXTENSION ASSEMBLY - FAILURE, TOTAL

Factual Information

Pilot Information

Certificate:	Private	Age:	48,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	July 21, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	869 hours (Total, all aircraft), 600 hours (Total, this make and model), 761 hours (Pilot In Command, all aircraft), 56 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N8043Y
Model/Series:	PA-30 PA-30	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	301154
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	125 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	3680 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	IO-320B
Registered Owner:	LAKELAND CONSTRUCTION	Rated Power:	160 Horsepower
Operator:	LAKELAND CONSTRUCTION	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 MIA82DA083

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	10 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	78°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	LAKELAND , FL	Type of Flight Plan Filed:	None
Destination:	PLACIDA , FL	Type of Clearance:	None
Departure Time:	15:20 Local	Type of Airspace:	

Airport Information

Airport:	ROTONDA X54	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	
Runway Length/Width:	4000 ft / 50 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	26.849496,-82.279441(est)

Page 3 of 4 MIA82DA083

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: March 24, 1983

Last Revision Date:
Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=72245

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 MIA82DA083