



Aviation Investigation Final Report

Location:	SCHROON LAKE, New York	Accident Number:	NYC82DA182
Date & Time:	August 3, 1982, 16:15 Local	Registration:	N6676B
Aircraft:	CESSNA 310C	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Ferry		

Analysis

THE BRAKES FAILED DURING LANDING ROLL AND THE AIRCRAFT WENT OFF THE END OF THE RUNWAY DAMAGING THE PROP AND NOSE GEAR. THE LEFT BRAKE WAS FOUND INOPERATIVE AND THE RIGHT BRAKE HAD EXCESSIVELY WORN PUCKS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN
Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR,NORMAL BRAKE SYSTEM - FAILURE,TOTAL
2. (C) MAINTENANCE,INSPECTION - INADEQUATE - OTHER MAINTENANCE PERSONNEL

Factual Information

Pilot Information

Certificate:	Private	Age:	Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim	Last FAA Medical Exam:	August 2, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1620 hours (Total, all aircraft), 220 hours (Total, this make and model), 1596 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N6676B
Model/Series:	310C 310C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	35776
Landing Gear Type:	Retractable - Tricycle	Seats:	5
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	4830 lbs
Time Since Last Inspection:	37 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	3132 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	IO-470-D
Registered Owner:	DONALD R. RUTH	Rated Power:	260 Horsepower
Operator:	DONALD R. RUTH	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	40 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	BUTLER-ROE , PA (3G9)	Type of Flight Plan Filed:	None
Destination:	COLTS NECK , NJ	Type of Clearance:	None
Departure Time:	14:15 Local	Type of Airspace:	

Airport Information

Airport:	SCHROON LAKE 4B7	Runway Surface Type:	Gravel
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	3164 ft / 50 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	43.830757,-73.730728(est)

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Original Publish Date: August 3, 1983

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=72572>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).