



Aviation Investigation Final Report

Location: SOLDOTNA, Alaska Accident Number: ANC82DA061

Date & Time: July 12, 1982, 13:30 Local Registration: N5276D

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

AFTER LANDING AT A PRIVATE AIRSTRIP THE PILOT TAXIED INTO A PARKED TRUCK. THE LEFT WING OF THE AIRCRAFT WAS SUBSTANTIALLY DAMAGED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI - FROM LANDING

Findings

1. (C) CLEARANCE - MISJUDGED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Student	Age:	37,Male
Airplane Rating(s):		Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 18, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	165 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N5276D
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	50174
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2650 lbs
Time Since Last Inspection:	30 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3400 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	0-470-K
Registered Owner:	JAMES WALTER HAWKINS	Rated Power:	230 Horsepower
Operator:	JAMES WALTER HAWKINS	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 ANC82DA061

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	SXQ	Distance from Accident Site:	22 Nautical Miles
Observation Time:	13:50 Local	Direction from Accident Site:	220°
Lowest Cloud Condition:	Unknown	Visibility	30 miles
Lowest Ceiling:	Broken / 7000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	60°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	ANCHORAGE , AK	Type of Flight Plan Filed:	None
Destination:	SOLDOTNA , AK	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	MACKEYS LAKES AK33	Runway Surface Type:	Gravel
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	60.320846,-150.790237(est)

Page 3 of 4 ANC82DA061

Administrative Information

Investigator In Charge (IIC):

Additional Participating

Persons:

Original Publish Date: July 12, 1983

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=72639

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ANC82DA061