



# **Aviation Investigation Final Report**

Location: ST. PAUL, Minnesota Accident Number: CHI82DA319

Date & Time: August 22, 1982, 17:19 Local Registration: N76778

Aircraft: CESSNA 120 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

#### **Analysis**

PILOT DID NOT STOW STARTER CRANK PROPERLY. DURING A LANDING THE AIRCRAFT TOUCHED DOWN ALMOST SIDEWAYS, WENT DOWN ON A WINGTIP AND UP ON ITS NOSE. THE STARTER CRANK WAS FOUND JAMMED IN THE RUDDER CONTROLS.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: LANDING - FLARE/TOUCHDOWN

**Findings** 

1. (C) FLIGHT CONTROL, RUDDER - JAMMED

2. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

## **Factual Information**

#### **Pilot Information**

Certificate:		Age:	49,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown None	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	2600 hours (Total, all aircraft), 335 hours (Total, this make and model), 25 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N76778
Model/Series:	120 120	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	1121
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	3 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1822 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	C-85-12
Registered Owner:	EDWARD B. THOMPSON	Rated Power:	85 Horsepower
Operator:	EDWARD B. THOMPSON	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 CHI82DA319

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	15 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	340°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	78°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	BLAKESBURG , IA (C )	Type of Flight Plan Filed:	None
Destination:	ST. PAUL , MN (C )	Type of Clearance:	None
Departure Time:	01:33 Local	Type of Airspace:	

### **Airport Information**

Airport:	ST. PAUL DOWNTOWN STP	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	3	IFR Approach:	None
Runway Length/Width:	5401 ft / 150 ft	VFR Approach/Landing:	None

### Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.930561,-93.08023(est)

Page 3 of 4 CHI82DA319

#### **Administrative Information**

**Investigation Docket:** 

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: August 22, 1983

Last Revision Date:
Investigation Class: Class
Note:

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

https://data.ntsb.gov/Docket?ProjectID=72706

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CHI82DA319