

# **Aviation Investigation Final Report**

Location:	TIPTON, Iowa		Accident Number:	MKC82DA035
	·			
Date & Time:	February 21, 1982, 1	4:00 Local	Registration:	N64998
Aircraft:	CESSNA	152	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional			

### **Analysis**

THE STUDENT PILOT SAID THAT HE WAS ON THE TAKEOFF ROLL WHEN THE AIRCRAFT VEERED LEFT AND COLLIDED WITH A SNOWBANK BESIDE THE RUNWAY. HE REPORTED THAT THE RUNWAY WAS CLEAR AND DRY, AND THE WIND WAS NOT A FACTOR.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings

(C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
(F) LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND
GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings 4. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - SNOWBANK

## **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	24,Male
Airplane Rating(s):		Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 16, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	54 hours (Total, all aircraft), 54 hours (Total, this make and model), 26 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

#### Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N64998
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	15281523
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1675 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1577 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-235-L2C
Registered Owner:	GREEN CASTLE AVIATION INC,	Rated Power:	110 Horsepower
Operator:	TIPTON FLIGHT SCHOOL	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

#### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CID	Distance from Accident Site:	26 Nautical Miles
Observation Time:	13:51 Local	Direction from Accident Site:	283°
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	320°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	41°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	TIPTON , IA (8C4)	Type of Flight Plan Filed:	None
Destination:	TIPTON , IA (8C4 )	Type of Clearance:	None
Departure Time:	14:00 Local	Type of Airspace:	

## **Airport Information**

Airport:	MATHEWS MEMORIAL 8C4	Runway Surface Type:	Concrete
Airport Elevation:	0 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	29	IFR Approach:	None
Runway Length/Width:	3000 ft / 60 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	41.76987,-91.119194(est)

#### Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	February 21, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=72820

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.