



Aviation Investigation Final Report

Location: WEST PLAINS, Missouri Accident Number: MKC82DA141

Date & Time: August 9, 1982, 19:30 Local Registration: N2319V

Aircraft: CESSNA 140 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT WAS PRACTICING SHORT FIELD TAKEOFFS AND MANEUVERED TO CLEAR A 50 FOOT BARRIER. HE STALLED THE AIRCRAFT AND WAS UNABLE TO RECOVER BEFORE IMPACTING THE GROUND, NOSE AND RIGHT WING FIRST.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

2. (C) STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

3. (F) TERRAIN CONDITION - OPEN FIELD

Page 2 of 5 MKC82DA141

Factual Information

Pilot Information

Certificate:	Commercial	Age:	48,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	645 hours (Total, all aircraft), 360 hours (Total, this make and model), 583 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N2319V
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	14555
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	38 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4458 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	C-85
Registered Owner:	RAYMOND L. FINE	Rated Power:	85 Horsepower
Operator:	RAYMOND L. FINE	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC82DA141

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	SGF	Distance from Accident Site:	80 Nautical Miles
Observation Time:	19:50 Local	Direction from Accident Site:	100°
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	15 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	79°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	WEST PLAINS , MO (H63)	Type of Flight Plan Filed:	None
Destination:	WEST PLAINS , MO (H63)	Type of Clearance:	None
Departure Time:	19:30 Local	Type of Airspace:	

Airport Information

Airport:	WEST PLAINS H63	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	3200 ft / 75 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	36.740608,-91.859016(est)

Page 4 of 5 MKC82DA141

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date: August 9, 1983

Last Revision Date:
Investigation Class: Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=73010

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available hereal/

Page 5 of 5 MKC82DA141