



Aviation Investigation Final Report

Location: Palmer, Alaska Accident Number: ANC12CA029

Date & Time: March 30, 2012, 14:00 Local Registration: N266V

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Low altitude operation/event **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot stated that during a low-level reconnaissance pass of a landing site on a snow-covered glacier, flat light conditions made it difficult to discern topographical features. During the pass, the airplane's left wheel/ski struck the ground, and the left main landing gear collapsed. The left wing subsequently struck the snow-covered ice, sustaining substantial damage to the left wing, left wing lift strut, and fuselage.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain adequate clearance from terrain during low-level maneuvering.

Findings

Aircraft Altitude - Not attained/maintained

Personnel issues Incorrect action performance - Pilot

Environmental issues Flat light - Contributed to outcome

Factual Information

History of Flight

Maneuvering-low-alt flying	Low altitude operation/event (Defining event)
Maneuvering-low-alt flying	Collision with terr/obi (non-CFIT)

Pilot Information

Certificate:	Private	Age:	47,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	September 15, 2011
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	500 hours (Total, all aircraft), 400 hours (Total, this make and model), 500 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 2 of 5 ANC12CA029

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N266V
Model/Series:	180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	31215
Landing Gear Type:	Tailwheel; Ski/wheel	Seats:	4
Date/Type of Last Inspection:	November 1, 2011 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:	20 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Teledyne Continental Motors
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	O-520 Series
Registered Owner:	DAVID B EIBECK	Rated Power:	300 Horsepower
Operator:	DAVID B EIBECK	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.94 inches Hg	Temperature/Dew Point:	-2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Anchorage, AK (Z41)	Type of Flight Plan Filed:	None
Destination:	Palmer, AK	Type of Clearance:	None
Departure Time:	13:00 Local	Type of Airspace:	

Page 3 of 5 ANC12CA029

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	61.186389,-148.592498(est)

Page 4 of 5 ANC12CA029

Administrative Information

Investigator In Charge (IIC):	Johnson, Clinton
Additional Participating Persons:	Randy S Smith; Federal Aviation Administration - Operations; Anchorage, AK
Original Publish Date:	June 28, 2012
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=83352

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC12CA029