Attendance Complete
16-09-2014 20:39:07

Vessel Name : EL FARO
Call/MMSI   : WFJK / 368208000
IMO Number : 7395351
Ship Owner : SeaStar Lines

Service Ticket# : 8000241496
Service Order# : 510944
Installer   : David Gunther
Location   : Jacksonville, FL, USA
         30-23.347N 081-32.396W

Version   : 5.01.17
Directory : C:\Program Files\Globe Wireless\GCC 5\

Reason for Attendance: i250 installation.

  Computer Info

Location   : File Room / Server room 2 decks below bridge
Computer   :   Serial #:
Supplied By : Customer
Processor   : GenuineIntel, x86 Family 6 Model 23 Stepping 10
Windows Ver : Microsoft Windows Server 2003 Service Pack 2
Proc Spd   : 2333 Mhz
Memory   : 2048.00 MB
Printer   :   Serial #:
Fixed Drives: C:447.05/250.19
CD Drives   : E:
Remv Drives :
Net Drives :
Com Ports   : COM2(\Device\Serial1),COM1(\Device\Serial0)
Condition   : GOOD
UPS Serial #:

  *** Computer Comments ***
Operational. Installed GCC and Globe Forms.

  Radio Info

No Radio

Satellite Info

Primary Satellite   : Globe i250 i250
  Location: Bridge
  Phone: 870773206528   Fax:
Provider   : Globe Wireless
Current Profile: i250
Satellite Operational Status: EXCELLENT

  *** Dial Profiles ***

i250   i250   10.205.42.12

  *** Satellite Comments ***
Crew did excellent job on pre-installation work. Installed Antenna on top of main mast and is currently
highest point should have no blockage. Tested system on voice and data both operational. BDU and UPS
is installed on bridge, UPS to be secured by crew. Currently BDU is powered by pre-existing UPS and will
be transferred to new Eaton UPS after extension cable is procured.

Sat info:

Inmarsat iFUSION Portal: 6.11.15 Inmarsat iFUSION Server: 6.11 Manufacturer ID Inmarsat Model Globe
i250-S3 Software Version R01.7.0 IMEI # 352187040026055 IMSI # 901112114202137 ADU Serial
14250029 BDU Serial # NB250TM141302605 MAC 00:0b:68:01:e2:ae Eaton UPS serial # GG451A0130

i250 operational. i4 left in service but disconnected from network and will be removed after i250 sea
trials.

  Network Info

Computer Name   : ELF-SERVER
IP Address   : 10.205.42.10
Local Mail Client: GWMail
# of Computers Networked: 10
Relay is installed and enabled
Remote Mail Client is

   GPS Info

GPS Type : Trimble / Internal
Com Port :
Status   : Enabled

Globe Forms Info

Globe Forms Version : 4.0.5.0

Globe Forms Location : C:\Program Files\Globe Wireless\GlobeForms\GlobeForms.exe

Forms Installed   Version
 NBIC   1.03.15
 NOAD   5.0.50

 *** Comments ***
Installed but may not be compatible with adobe acrobat 7.1.0 professional. Currently they use infopath for enoad and globe forms is not used and want the current adobe acrobat 7.1.0 left in service.

Training Provided To

Captain
Went over rebooting procedures and i250 access.

Attendance Summary

PC: Operational. Installed GCC and Globe Forms. GAV not required as advised by IT personnel ship is using symantec.

Sat: i250 in service using profile on GCC.

Network: Operational.

Forms: Installed but not operational at this time. May be used at a later date.

Installation complete pending Sea Trials.

   Repair Info

Suspected cause of failure: NA

        *** Equipment Replaced ***
         Old S/N   New S/N

Failed Items returned to:
 NA

Unused Items Disposition:
 NA

   Labor Summary

     Hours

Computer/Networking :   1
         Travel :   6
          Other : Sat i250:7.5

Please advise company that attendance is complete and vessel is ready to receive traffic via Globe Wireless.

I verify above work was done, and noted equipment replaced.

I also acknowledge that I am responsible for the return of items noted above (if any) to Globe Wireless at the first opportunity.
If not returned at the earliest possible time, my owners may be invoiced for that equipment.

_____ (Captain)
Mike Davidson

_____ (Installer)
David Gunther
(Assisted by IT Personnel)
5.01.17

Received: from MPD at Globe Wireless;
Tue, 16 Sep 2014 21:13 UTC
Message-id: 309609466