Photo 10: Right Propeller Spinner Showing Additional Contact Signatures