RECORD OF EMAIL

Albert P. Nixon
Senior Aviation Accident Investigator
Western Pacific Region

Date: June 17, 2019
Person Contacted: Brannon Mayer (Cirrus Air Safety Investigator)
NTSB Accident Number: WPR17FA150

Narrative:

On an email with Brannon Mayer, the following is a summary:

- A new key was made for the ignition switch.
- The new key worked and was checked out with no anomalies.
- The ignition switch was disassembled, and the internal contacts were in good condition and no FOD or corrosion was present.