OBSERVATION NOTE
SHIPBOARD

Vessel: S.S.	EL FARO	Date:	03/25/14
Lead Auditor:	Harry Rogers & John Lawrence	Observation Page #	1 of 1

Description of Observation(s):

1. A Master's review needs to be done before the ABS external audit.

2. The Semi-annual OWS Audit and the Annual vessel inspection by the PE are due.

3. The C/E had not completed the insertion of all of the changes at the time of the audit.

4. The vessel antenna diagram needs to be updated.

5. Several of the container walk way gratings on the main deck were found to be in need of repair.

6. The ORB and Related Info binder was found to be missing an update. TSI to provide.

Auditor Signature
(PRINT/SIGN)

Auditee Signature
(PRINT/SIGN)