DAILY RECORD OF FACILITY OPERATION

DATE Jul 7, 2015

CHECKED BY

LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	AIR TRAFFIC MANAGER
Charleston, SC	CHS	ATCT	CHS Daily Log	Stephanie Faison

	UTC TIME	REMARKS
	0400	M. KESTELOOT ON, BELOW NOTED.
		CFPL: TOWER WINDOW ABOVE CENRAP CONTROL PANEL LEAKING. AOCC NTFD.
		CFPL: FIRE ALARM PANEL IN ALARM ONCE A DAY, INTERNAL. TECHOPS AWARE.
		CFPL: ASR9 SC/COM ALARM, IN TRACON SINCE 8/15/13.
		CFPL: PILOTS REPORT BLEEDOVER ON 120.7.
		CFPL: SCIP CH A OTS.
		CFPL: BASEOPS DIRECT LINE IN TOWER LOUD STATIC, BASEOPS NOTIFIED.
		CFPL: ROTATING BEACON STUCK IN ON POSITION, BASEOPS NOTIFIED.
		CFPL: 119.85 PRI RX HAS STATIC. -- LT
	0400	RY 15/33 CLSD. -- LT
	0425	WCLC. -- LT
	0930	RWY 15/33 OPEN. -- JR
	0948	RADAR DE-COMBINED. TRACON OPEN. -- LT
	1000	P.COVERT ON. ABOVE NOTED. -- TC
	1158	15/33 RVR OTM. -- TC
	1239	LCS RLSD TO SEALORD. -- JK
	1327	K. YOUNG ON, ABOVE NOTED. -- KY
	1327	RVR RTS. -- KY
Q	1500	AIRCRAFT ACCIDENT, DEATH41, F16. -- KY
E	1700	RVR RY15/33 MIDFIELD OTS. -- KY
M	1702	CHS-M-2015/07/07-0001 -- RPA4468 -- KY
	1725	C. MASON ON ABOVE NOTED. -- CH
	1807	LCS RETURNED. -- CH
	2100	WCLC. -- CH
	0045	S.OLIVARES ON. ABOVE NOTED. -- SO
	0230	V.SAHIJRAM ON. ABOVE NOTED. -- VR
	0230	TRACON COMBINED TO TOWER. -- VR
	0300	RWY 15/33 CLSD PER NOTAM. -- VR
E	0334	RWY 21 PAPI OTS. BASE OPS NOTIFIED. -- VR

I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.

SIGNATURES(S) OF WATCH SUPERVISOR(S)

FAA Form 7230-4

DAILY RECORD OF FACILITY OPERATION

DATE	Jul 7, 2015

LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	CHECKED BY
Charleston, SC	CHS	ATCT	CHS Daily Log	AIR TRAFFIC MANAGER Stephanie Faison

UTC TIME	REMARKS
0359	COB. -- VR

I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.

SIGNATURES(S) OF WATCH SUPERVISOR(S)

FAA Form 7230-4