DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION ... SIGNATURE & CERTIFICATE NO. OF PERSON ...
				TOTALS brought forward from previous page
				Date: 5/31/16 TT: 8904.9 Service air and lubricated propeller. I certify that [redacted] propeller Has been inspected IAW 50 hrs. Inspection and with FAR 43 Appendix D And was determin[redacted] airworthy condition to return to service. Juan Carlos Marrero A&P [redacted]
7/12/16	9014.6	57.2		Removed this propeller from A/C N2395Z R/H position ATT: 8918.4 TSO 57.2. and installed this Prop. on A/C N21WW L/H position. ATT: 9014.6 TSO 57.2. Ops ck found normal for return to service. [redacted] A&P [redacted]
				Date: 8/3/16 TT: 9036.9 Service air and lubricated propeller. I certify that LH propeller Has been inspected IAW 50 hrs. Inspection and with FAR 43 Appendix D And was determined to be in airworthy condition to return to service [redacted] Juan Carlos Marrero A&P [redacted]
11/17/2016	10,338.6	129.9	9,087.3	DATE: 11/17/2016 A/C TIME 9,087.3 HOBBS N/A I CERTIFY THAT THIS Propeller HAS BEEN INSPECTED IN ACCORDANCE WITH A Annual INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION As per FAR 43 appendix D [redacted] IA [redacted] SIGNATURE CERTIFICATE NUMBER
				Date: 1/23/17 TT: 9136.4 Service air and lubricated propeller. I certify that LH propeller Has been inspected IAW 50 hrs. Inspection and with FAR 43 Appendix D And was determined to be in airworthy condition to return to service [redacted] Juan Carlos Marrero A&P [redacted]
				TOTALS-Carry forward to next page