RECORD OF EMAIL

Albert P. Nixon
Senior Aviation Accident Investigator
Western Pacific Region

Date: May 16, 2019
Person Contacted: Nicole Charnon (Continental Senior Air Safety Investigator)
NTSB Accident Number: WPR17FA150

Narrative:

On an email with Nicole Charnon, the following is a summary:

- Ignition switch was in both and all wiring was intact with no fraying, from the switch to the engine firewall.
- We tried to check the contacts with a voltmeter but the key broke and locked in place.