Date Created	Type	Pty	Primary Gang	Subdivision	Track Type	Sprt Prefix	Sprt Trk Nbr	MP From	MP To	Defect Detail	Scheduled Start Date	Scheduled End Date	Special Instr	Closure Code	Closed Date	Closed By	Closed Comments	Segment	Latitude	Longitude	Manager	Remedial Description	Remediated By	TI Name
3/27/2020	TI - TRACK INSPECTION	L		PHOENIX SUB	SIMN			9/15	9/15	999.12 - Missing - whole post (public crossings			Def Size: 0		3/27/2020	ENGG100		4984	33.41914121	-111.9435664	Gora, S. J	Repaired Before Traffic	ENGG100	Ball,DEL GLEN
4/13/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7400	PHOENIX SUB	SIMN			914.2	914.21		4/13/2020	4/13/2020	temp approach to bridge		4/13/2020	7400	temp approach to bridge	4984	33.43080197	-111.9436286	Gora, S. J			
5/8/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIDE	1	113	910.79	910.79	135.B1 - Improper fill between switch point and stock rail.			Def Size: 0		5/8/2020	ENGC284		4984	33.4442825	-111.9946804	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/8/2020	TI - TRACK INSPECTION			PHOENIX SUB	YARD	1	710	910.86	910.86	133.A17 - Obstruction in thergeway of frog.			Def Size: 0		5/8/2020	ENGC284		4984	33.44421445	-111.9934155	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/15/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7400	PHOENIX SUB	SIMN			912.1	912.1		5/15/2020	5/15/2020	maintenance grind overflow on frog		5/15/2020	7400	maintenance grind overflow on frog	4984	33.44270074	-111.9722292	Gora, S. J			
5/15/2020	TI - TRACK INSPECTION			PHOENIX SUB	YARD	1	701	912.17	912.17	121.E - Less than 2 bolts per rail at any joint in continuous welded rail.			Def Size: 0		5/15/2020	ENGC284		4984	33.44257276	-111.9710617	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/20/2020	INSTA - INSTALL ANCHORS	M	7443	PHOENIX SUB	SIMN			913.5	913.6		5/20/2020	5/20/2020	add replace anchors	Repair Completed	5/20/2020	7443	apply rail anchors on curve/haul material	4984	33.43732375	-111.9497036	Gora, S. J			
5/20/2020	INSTA - INSTALL ANCHORS	M	7443	PHOENIX SUB	SIMN			913.5	913.6		5/20/2020	5/20/2020	install anchors	Repair Completed	5/20/2020	7443	apply rail anchors on curve/haul material	4984	33.43732375	-111.9497036	Gora, S. J			
5/20/2020	TRUC - HAUL MATERIAL	M	7443	PHOENIX SUB	SIMN			913.5	913.6		5/20/2020	5/20/2020	haul anchors	Repair Completed	5/20/2020	7443	apply rail anchors on curve/haul material	4984	33.43732375	-111.9497036	Gora, S. J			
5/20/2020	MTRLD - MATERIAL DISTRIBUTE	M	7443	PHOENIX SUB	SIMN			913.5	913.6		5/20/2020	5/20/2020	distribute anchors	Repair Completed	5/20/2020	7443	apply rail anchors on curve/haul material	4984	33.43732375	-111.9497036	Gora, S. J			
5/21/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			914.33	914.33	133.A12 - Loose, worn, or missing frog bolts.			Def Size: 0		5/21/2020	ENGC284		4984	33.42890796	-111.9435835	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/21/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			914.33	914.33	133.A12 - Loose, worn, or missing frog bolts.			Def Size: 0		5/21/2020	ENGC284		4984	33.42890796	-111.9435835	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/21/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			914.33	914.33	133.A12 - Loose, worn, or missing frog bolts.			Def Size: 0		5/21/2020	ENGC284		4984	33.42890796	-111.9435835	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/27/2020	SO - SLOW ORDERS			PHOENIX SUB	SIMN			913.5	913.8	MANY SURFACING		6/3/2020	tonnage		5/30/2020 3:25	System		4984	33.43732375	-111.9497036	Gora, S. J			
5/27/2020	HAUL - HAUL EQUIPMENT	M	7443	PHOENIX SUB	SIMN			913	914		5/27/2020	5/27/2020	haul backhoe	Repair Completed	5/27/2020	7443	line curve/add anchors	4984	33.43629253	-111.9582668	Gora, S. J			
5/27/2020	INSTA - INSTALL ANCHORS	M	7443	PHOENIX SUB	SIMN			913	914		5/27/2020	5/27/2020	apply anchors	Repair Completed	5/27/2020	7443	line curve/add anchors	4984	33.43629253	-111.9582668	Gora, S. J			
5/27/2020	MTRLD - MATERIAL DISTRIBUTE	M	7443	PHOENIX SUB	SIMN			913	914		5/27/2020	5/27/2020	lay out anchors	Repair Completed	5/27/2020	7443	line curve/add anchors	4984	33.43629253	-111.9582668	Gora, S. J			
5/27/2020	INSTA - INSTALL ANCHORS	M	7443	PHOENIX SUB	SIMN			913	914		5/27/2020	5/27/2020	apply anchors	Repair Completed	5/27/2020	7443	line curve/add anchors	4984	33.43629253	-111.9582668	Gora, S. J			
5/27/2020	SPTMP - SPOT TAMP	M	7443	PHOENIX SUB	SIMN			913	914		5/27/2020	5/27/2020	line curve	Repair Completed	5/27/2020	7443	line curve/add anchors	4984	33.43629253	-111.9582668	Gora, S. J			
5/27/2020	TSL - SURFACE LINE TRACK	M	7443	PHOENIX SUB	SIMN			913	914		5/27/2020	5/27/2020	line out curve	Repair Completed	5/27/2020	7443	line curve/add anchors	4984	33.43629253	-111.9582668	Gora, S. J			
5/28/2020	SFBF - SAFETY BRIEFING	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	safety meeting	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/28/2020	TRUL - TRAVEL TO LOCACTION	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	drive truck to jobsite	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/28/2020	TRUL - TRAVEL TO LOCACTION	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	drive truck to job site #2	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/28/2020	TRUL - TRAVEL TO LOCACTION	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	drive truck to office	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/28/2020	SURF - MISC. SURFACE WORK	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	line switches for equip	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/28/2020	SURF - MISC. SURFACE WORK	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	track travel equip	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/28/2020	SURF - MISC. SURFACE WORK	M	7472	PHOENIX SUB	SIMN			913.8	913.8		5/28/2020	5/28/2020	plot curve	Repair Completed	6/2/2020	7472	none	4984	33.43649685	-111.9447475	Gora, S. J			
5/29/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			912.6	912.6	133.A13 - Loose, worn, or missing guard rail bolts.			Def Size: 0		5/29/2020	ENGC284		4984	33.44102358	-111.9641428	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
5/29/2020	SO - SLOW ORDERS			PHOENIX SUB	SIMN			913.5	914.25	MANY SURFACING		6/3/2020	step up		6/3/2020 3:21	System		4984	33.43732375	-111.9497036	Gora, S. J			
6/1/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIDE	1	113	910.79	910.79	135.B1 - Improper fill between switch point and stock rail.			Def Size: 0		6/1/2020	ENGC284		4984	33.4442825	-111.9946804	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
6/1/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIDE	1	113	911.94	911.94	133.A12 - Loose, worn, or missing frog bolts.			Def Size: 0		6/1/2020	ENGC284		4984	33.4431251	-111.975018	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
6/15/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			912.2	912.2	121.F2 - Loose joint bars (CWR).			Def Size: 0		6/15/2020	ENGC284		4984	33.4424474	-111.9705644	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
6/22/2020	TI - TRACK INSPECTION			PHOENIX SUB	YARD	6	110	914.78	914.78	135.D - Heel of switch inwecure.			Def Size: 0		6/22/2020	ENGC284		4984	33.42234823	-111.9435731	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
6/22/2020	TI - TRACK INSPECTION			PHOENIX SUB	YARD	6	110	914.33	914.33	135.D - Heel of switch inwecure.			Def Size: 0		6/22/2020	ENGC284		4984	33.42890796	-111.9435835	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
6/27/2020	SO - SLOW ORDERS			PHOENIX SUB	SIMN			913.9	914.2	Bridge Condition		9/21/2020	Bridge ties must be replaced		7/14/2020 3:25	System		4984	33.43515837	-111.9440941	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7443	PHOENIX SUB	SIMN			914	914		6/27/2020	6/27/2020	derailment		6/27/2020	7443	derailment	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7452	PHOENIX SUB	SIMN			913.9	914		6/27/2020	6/27/2020	Worked behind derailment on Phoenix sub		6/27/2020	7452	Worked behind derailment on Phoenix sub	4984	33.43515837	-111.9440941	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7448	PHOENIX SUB	SIMN			913.9	914		6/27/2020	6/27/2020	tempe bridge derailment installed ties and gage track		6/27/2020	7448	tempe bridge derailment installed ties and gage track	4984	33.43515837	-111.9440941	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/27/2020	6/27/2020	replace ties		6/27/2020	7423	replace ties	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/27/2020	6/27/2020	hand tamp		6/27/2020	7423	hand tamp	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/27/2020	6/27/2020	restore walkway		6/27/2020	7423	restore walkway	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7422	PHOENIX SUB	SIMN			914	915		6/27/2020	6/27/2020	Replaced 600 spikes		6/27/2020	7422	Replaced 600 spikes	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7422	PHOENIX SUB	SIMN			914	915		6/27/2020	6/27/2020	Gaged 1000' of rail		6/27/2020	7422	Gaged 1000' of rail	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7422	PHOENIX SUB	SIMN			914	915		6/27/2020	6/27/2020	Adjusted anchors		6/27/2020	7422	Adjusted anchors	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7422	PHOENIX SUB	SIMN			914	915		6/27/2020	6/27/2020	Hand Tamped 40'		6/27/2020	7422	Hand Tamped 40'	4984	33.43370581	-111.9439407	Gora, S. J			
6/27/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7422	PHOENIX SUB	SIMN			914	915		6/27/2020	6/27/2020	Restored ballast		6/27/2020	7422	Restored ballast	4984	33.43370581	-111.9439407	Gora, S. J			
6/28/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7452	PHOENIX SUB	SIMN			913.9	914		6/28/2020	6/28/2020	Worked derailment on Phoenix sub		6/28/2020	7452	Worked derailment on Phoenix sub	4984	33.43515837	-111.9440941	Gora, S. J			
6/28/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/28/2020	6/28/2020	replace fastners		6/28/2020	7423	replace fastners	4984	33.43370581	-111.9439407	Gora, S. J			
6/28/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/28/2020	6/28/2020	gauge		6/28/2020	7423	gauge	4984	33.43370581	-111.9439407	Gora, S. J			
6/28/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/28/2020	6/28/2020	replace anchors		6/28/2020	7423	replace anchors	4984	33.43370581	-111.9439407	Gora, S. J			
6/28/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7423	PHOENIX SUB	SIMN			914	914		6/28/2020	6/28/2020	adjust anchors		6/28/2020	7423	adjust anchors	4984	33.43370581	-111.9439407	Gora, S. J			
7/1/2020	UPMF - UNPLANNED TASK FROM MAINFRAME	M	7407	PHOENIX SUB	SIMN			913.9	914.2		7/1/2020	7/1/2020	APPLY ANCHORS THROUGH SALT RIVER BRIDGE. REPLACED 2 CROSSTIES. HAND TAMPED 100FT ON EAST APPROACH		7/1/2020	7407	APPLY ANCHORS THROUGH SALT RIVER BRIDGE. REPLACED 2 CROSSTIES. HAND TAMPED 100FT ON EAST APPROACH	4984	33.43515837	-111.9440941	Gora, S. J			
7/1/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIDE	1	113	911.94	911.94	133.A14 - Loose, worn or missing, guard rail clamps, wedge, separator block, end block, or other components.			Def Size: 0		7/1/2020	ENGC284		4984	33.4431251	-111.975018	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
7/1/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIDE	1	113	911.94	911.94	133.A14 - Loose, worn or missing, guard rail clamps, wedge, separator block, end block, or other components.			Def Size: 0		7/1/2020	ENGC284		4984	33.4431251	-111.975018	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
7/2/2020	TMJNT - TAMP JOINTS	M	7406	PHOENIX SUB	SIMN			914.1	914.1				temp under weld	Repair Completed	7/2/2020	7452	helped welders	4984	33.4322541	-111.9437844	Gora, S. J			
7/2/2020	TRUL - TRAVEL TO LOCACTION	M	7406	PHOENIX SUB	SIMN			914.1	914.1				lvl to phx mp 914.1	Repair Completed	7/2/2020	7452	helped welders	4984	33.4322541	-111.9437844	Gora, S. J			
7/2/2020	WEBJ - WELD BRIDGE JOINTS	M	7406	PHOENIX SUB	SIMN			914.1	914.1				weld jnt 914.1 1 of 2	Repair Completed	7/2/2020	7406	weld jnt adj anchors	4984	33.4322541	-111.9437844	Gora, S. J			
7/2/2020	WEBJ - WELD BRIDGE JOINTS	M	7406	PHOENIX SUB	SIMN			914.1	914.1				weld jnt 914.1 2 of 2	Repair Completed	7/2/2020	7452	helped welders	4984	33.4322541	-111.9437844	Gora, S. J			
7/10/2020	SURF - MISC. SURFACE WORK	M	7443	PHOENIX SUB	SIMN			914.5	914.5		7/10/2020	7/10/2020	dump ballast for surface gang.	Repair Completed	7/13/2020	7414	surf bridge, rep 914.2, phoenix sub	4984	33.42642984	-111.9435796	Gora, S. J			
7/11/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			910.26	910.26	127.AE - Insufficient fasteners in a track segment.			Def Size: 0		7/11/2020	ENGH169		4984	33.44426562	-112.0042408	Gora, S. J	Repaired Before Traffic	ENGH169	Estrada,Gabriel.
7/20/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			910.5	910.5	37.C3 - Excessive vegetation in bagpaths and around switches that interferes with employees performing normal trackside duties.			Def Size: 0		7/20/2020	ENGC284		4984	33.4442711	-111.9999116	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
7/20/2020	TI - TRACK INSPECTION			PHOENIX SUB	SIMN			910.6	910.6	37.E3 - Vegetation brushing sides of rolling stock that prevents employees from visually inspecting moving equipment from their normal duty stations.			Def Size: 0		7/20/2020	ENGC284		4984	33.44427503	-111.9981077	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A
7/28/2020	TI - TRACK INSPECTION	L		PHOENIX SUB	SIMN			914.3	914.3	999.24 - High crossing surface lag screw			Def Size: 0		7/28/2020	ENGC284		4984	33.42934527	-111.9435839	Gora, S. J	Repaired Before Traffic	ENGC284	Sheppard,Chester A