WPR18FA211 ATC Transcripts.

August 05, 2018 ALL TIMES BELOW ARE COORDINATED UNIVERSALTIME UNLESS OTHERWISE SPECIFIED

1925: N727RP called LCl inbound to SNAfor landing. Local Control l (LC1) issued instructions to make right traffic for RY20R.

1927: LCl asked N727RP if he could accept RY20L for landing which he could not accept. LCl issued instructions to hold over South Coast Plaza for sequencing.

1928: N727RP indicated he could now accept RY20L for landing and LCl issued instructions to make a left 270 turn and cross over the airport at 1,300 for left traffic RY20L.

1929: N727RP declared an emergency and crashed 1.5 miles west of SNA airport.