Date 4/26/2011

W/O# 11333

WOODLAND AVIATION

Propeller Logbook Entry

CRS AWKR298C

25170 Aviation Ave., Davis, CA 95616

AIRCRAFT: 7229X

S/N CE-1063

Tach Time	33693.1
TTAF	3929.9
Prp TSN	3929.9
Prp TSO	429.5

COMPLETED 100HR INSPECTION THIS DATE USING RAYTHEON INSPECTION FORM P/N 98-32227Q AS A GUIDE. ALL WORK DONE IN ACCORDANCE WITH APPLICABLE MAINTENANCE MANUALS.
C/W 100 HOUR STROBE CHECK OF PROPELLER. COMPLY WITH AIRWORTHINESS DIRECTIVE **2007-08-04**, EFFECTIVE 5/17/2007 MCCAULEY PROPELLER BY INSPECTION OF PROPELLER, INSTRUMENT PANEL IS PLACARDED.
I CERTIFY THAT THIS AIRCRAFT/ENGINE/PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AN UNAIRWORTHY CONDITION. A LIST OF UNAIRWORTHY DISCREPANCIES HAS BEEN PROVIDED TO THE OWNER

DAMON SCHMIDT [redacted]

L3 communications
Avionics Systems

September 9, 2011 | N7229X | Beechcraft F33A
Serial No. CE1063 | Tach 3471.1 | ACTT 4031.9
Propeller: | **P/N 3A32C406B** | **S/N 922048**
Total time 4031.9 | **TSOH 531.5**

C/W Annual / 100 hour Inspection of the Propeller. Next inspection due @ 4131.9 or 9/9/2012
Dressed all blades, painted face and back sides Researched AD's thru 2011-18
All work done IAW McCauley maintenance Manual and HBC F33 series Maintenance Manual
This propeller/governor were inspected in Accordance with an Annual Inspection per Hawker Beechcraft F33A Bonanza Scheduled Inspection Report, chapter 5-20 of Maintenance Manual

Bruce R Temple [redacted]

6/

2

Western Aircraft Propeller Service
42313 SE Oral Hull Road #2
Sandy, OR 97055
Repair Station FQ6R544N
WO# 27027 McCauley Propeller 3A32C406-B/82NDB-2
Hub Serial – 831440 Blade Ser-1.MG085 2.MG086 3.MG105
Overhaul and Recondition Propeller.

[redacted]

03/16/2022 DATE

Repairman

component identified above was inspected or repaired in accordance with Current FAA Regulations and found airworthy for return to service. Pertinent Details are on file at this agency under work order number.

FAA Repair Station FQ6R544N TSO-0000 TSN –4222.00 UKN

Date: 3/23/2022; Aircraft: N444PM
Tach: 481.7, PropTT: 4222, PropTSO: 00.0 - Installed McCauley propeller 3A32C406-B, s/n 831440, On Beechcraft V35B, s/n D-9905, registration N444PM after overhaul by Western Aircraft Propeller, RS# FQ6R544N, under WO# 27027 dated 03/16/2022. This propeller was removed by unknown from Beechcraft F33A, s/n CE-1063, registration N7229X at unknown date. Reinstalled prop governor after overhaul by Olympia Propeller Governor, LLC, RS# 1OPR610B, under WO# 0002538 dated 12/21/2021. Operational and leak check good.
Aero Maintenance, Inc.
Shop Order 21-0896

[redacted]