Work Order Detail

432-2017-62

massDOT
Massachusetts Department of Transportation
Rail & Transit Division

Job Status: CLOSED
Opened By: RICH RACHELS
Opened: 01/03/2017 22:20
First Labor: 01/04/2017 00:00
Finished By: WESLEY DUDOVICZ
Finished: 01/27/2017 19:19
Closed By: WESLEY DUDOVICZ
Closed: 01/27/2017 19:19

Unit #: 01510 68-SILVERBIRD SINGLE REBUILD #
Dept: 432 CABOT RTL SHOPS
MUP #:
Eq Warranty: NO
Job Type: REPAIR
Hub Miles At W.O. Open: 2429096
LTD Miles At W.O. Open: 2429096

Work Order Comments

RELUGGED #3 MOTOR LEAD, R/R`D KNIFE CN CONDOMS

Warranty	Task	& Comments	Hours	Labor Cost	Parts Cost	Total Cost
NO	C-K	PASSENGER COMPARTMENT	2.00	PII	[redacted]	[redacted]
NO	C-	BODY & FRAME	4.00	PII	[redacted]	[redacted]
NO	H-	HEAT - VENTILATOR AND AIR CONDITIONING SYSTEMS	8.00	PII	[redacted]	[redacted]
NO	E-S13	MARKER LIGHTS	8.00	PII	[redacted]	[redacted]
NO	J-P3	PNEUMATIC CONTROLS-COUPLERS/DG	32.00	PII	[redacted]	[redacted]
NO	A-	AIR SYSTEM	0.00	PII	[redacted]	[redacted]
NO	X-	AUTO. TRAIN CONTROL (ATO/ATC)	2.50	PII	[redacted]	[redacted]
NO	A-A2	AUTO DRAIN VAL.(SPIT.VAL)ACO	32.00	PII	[redacted]	[redacted]
NO	A-L	AIR LINES & FITTINGS - AIR SUPPLY	112.00	PII	[redacted]	[redacted]
NO	C-D1A	SIDE DESTINATION SIGNS	8.00	PII	[redacted]	[redacted]
NO	P-CA	CONTROL CASE- PROPULSION	40.00	PII	[redacted]	[redacted]
NO	P-Y1A	RATING- PROPULSION	8.00	PII	[redacted]	[redacted]
NO	P-TA	TRACTION MOTOR- PROPULSION	16.00	PII	[redacted]	[redacted]
NO	P-MA	CINESTON-ELECTRICAL-PROPULSION	32.00	PII	[redacted]	[redacted]

* Not Inv = Scanned or not purchased via FMIS

Work Order Detail

432-2017-62

massDOT Massachusetts Department of Transportation Rail & Transit Division

Task & Date		Employee		Hours	Cost	Comments
A-L	01/04/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	IDENTIFY AIR LEAKS
A-L	01/04/2017	69245	FISKE, JOSEPH	8.00	PII [redacted]	IDENTIFY AIR LEAKS
A-L	01/04/2017	70054	DESOUSA, MATHEW	8.00	PII [redacted]	IDENTIFY AIR LEAKS
A-L	01/05/2017	70054	DESOUSA, MATHEW	8.00	PII [redacted]	REPAIR PROPULSION AIR LEAKS,
A-L	01/06/2017	70054	DESOUSA, MATHEW	8.00	PII [redacted]	REPAIR PROPULSION AIR LEAKS
A-L	01/13/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	CONTINUE REPAIRING AIR LEAKS
A-L	01/13/2017	70054	DESOUSA, MATHEW	8.00	PII [redacted]	SET AIR COMPRESSOR OFF TIMES AND ADJUST PROP REGULATOR
A-L	01/19/2017	65587	HORAN, RICHARD	8.00	PII [redacted]	REPAIR AIR LEAKS
A-L	01/20/2017	70809	BROBERG, PAUL	8.00	PII [redacted]	CHECK OFF TIMES AND ADJUST BRAKE PRESSURES
A-L	01/23/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	SET BRAKE PRESSURES
A-L	01/23/2017	70809	BROBERG, PAUL	8.00	PII [redacted]	SET BRAKE PRESSURES
A-L	01/24/2017	70809	BROBERG, PAUL	8.00	PII [redacted]	SET AND VERIFY BRAKE PRESSURES
A-L	01/27/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	R & R TEST FITTINGS
A-L	01/27/2017	70054	DESOUSA, MATHEW	8.00	PII [redacted]	R & R PROPULSION REGULATORS AND HOSES
C-D1A	01/20/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	R & R SCROLL ON SIDE DESTIATION SIGN AND WIRE IN NEW BALLAST
E-S13	01/25/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	R & R GS MARKER LIGHT
J-P3	01/20/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	FINISH COUPLER MANIFOLD AND TEST OK
J-P3	01/23/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	T/S NO #1 END MARKER LIGHTS
J-P3	01/24/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	T/S TO CORODED WIRE #52 AND R & R CS TOP MARKER LIGHT
P-CA	01/05/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	R & R BURNT UMA9 CONTACTOR AND LINE SWITCH
P-CA	01/06/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	REPAIR/ REPLACE BURNT HIGH VOLTAGE WIRING
P-CA	01/10/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	R & R CINESTON
P-CA	01/11/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	R & R CINESTON
P-CA	01/13/2017	69476	COSTELLO, CRAIG	8.00	PII [redacted]	CONTINUE HIGH VOLTAGE WIRING REPAIR
P-MA	01/12/2017	70809	BROBERG, PAUL	8.00	PII [redacted]	R & R HEATER DUCT START CINESTON INSTALL
P-MA	01/13/2017	70809	BROBERG, PAUL	8.00	PII [redacted]	INSTALL AND WIRE CINESTON
P-MA	01/25/2017	66422	KORONA, BRIAN	8.00	PII [redacted]	REVIEW CINESTON TEST PROCEDURE WITH ENGINEERING
P-MA	01/25/2017	70809	BROBERG, PAUL	8.00	PII [redacted]	REVIEW CINESTON TEST PROCEDURE WITH ENGINEERING

* Not Inv = Scanned or not purchased via FMIS

Work Order Detail

432-2017-62

Task & Date		Employee		Hours	Cost	Comments
P-Y1A	01/27/2017	67910	CAFETEIRO, RYAN	4.00	PII	CHECKED/ADJUSTED THE RATES ON THE TT
P-Y1A	01/27/2017	68710	GULLOTTI-HOWARD, KRISTIN	4.00	PII	CHECKED/ADJUSTED THE RATES ON THE TT
J-P3	01/18/2017	66422	KORONA, BRIAN	8.00	PII	REMOVE COUPLER CONTROL MANIFOLD AND INSTALL REBUILT UNIT
X-	01/07/2017	71254	BENITEZ, ROBERTO	2.50	PII	ATO BYPASS/MANRL LIST - CABSIGNAL TESTING + CALIBRATION
A-A2	01/04/2017	69477	KENNEDY, SHAWN	8.00	PII PII	SPIT VALVE MOD
A-A2	01/05/2017	69477	KENNEDY, SHAWN	8.00	PII	SPIT VALVE MOD
A-A2	01/17/2017	69477	KENNEDY, SHAWN	8.00	PII	AUTO DRAIN MOD
A-A2	01/17/2017	70882	HARRIS, LINDSEY	8.00	PII	AUTO DRAIN MOD
C-	01/25/2017	70467	PICARDI, TIMOTHY	4.00	PII PII	ASSEMBLE CAB SHEET METAL
C-K	01/25/2017	69477	KENNEDY, SHAWN	2.00	PII	INSTALL HAND STRAPS
P-TA	01/26/2017	17110	WONG, YING-HAP	8.00	PII	SEE COMMENTS
P-TA	01/26/2017	17145	DEVLIN, MICHAEL	8.00	PII	SEE COMMENTS
H-	01/27/2017	71755	TRAYERS, MICHAEL	8.00	PII	REPLACE AND TEST OHBM RESISTORS...

* Not Inv = Scanned or not purchased via FMIS

Work Order Detail

432-2017-62

massDOT
Massachusetts Department of Transportation
Rail & Transit Division

Task & Date		Part	Description	Installed Serial No	Removed Serial No	Comments	Not Inv *	Qty	Cost
A-L	01/23/2017	02574698	NOT ASSIGNED; SIDE-SCROLL DESTINATION SIGNS - #1 & 2 CARS					1	PII
A-L	01/06/2017	03501529	HOSE; AIR HOSE W/ FITTINGS 15 IN. LONG FOR C.D. CAR					4	PII
A-L	01/06/2017	03575038	GASKET; GASKETS WH UB-186 MA GNET VALVE CASE OF 25					2	PII
H-	01/27/2017	02693025	RESISTOR; RESISTOR - SPEED CONTROL OVERHEAD BLOWER MOTOR 60 OHM #T-14736-#1SS A/					2	PII
P-CA	01/11/2017	03501006	CONTACT; LEVER-CONTACT(UMA CO NTACTOR)					2	PII
P-CA	01/11/2017	03501190	CONNECTOR; CONNECTOR INTERLOCK					2	PII
P-CA	01/11/2017	03501191	CONTACT; FINGER-CONTACT WSTGH SE INTERLOCK					2	PII
P-CA	01/06/2017	03501345	COIL; COIL-BLOW-OUT					1	PII
P-CA	01/06/2017	83024040	REBUILDABLE; UMA-9 CONTACTOR #1 & #2 CARS					3	PII

Service Request/Defects Symptom	Date Entered	Hub	Comments
	10/27/2016 13:45	2418717	UNCOUPLER CYLINDER LEAKS WHEN ENERGIZED

Summary Costs

Total Labor Cost:	PII
Parts Cost:	
Inv:	PII
Not Inv:	[redacted]
Total Parts Cost:	PII
Total W.O. Cost:	PII

* Not Inv = Scanned or not purchased via FMIS