National Transportation Safety Board
Office of Highway Safety
Washington, DC 20594

HWY24MH013

HUMAN PERFORMANCE ATTACHMENT

Mack Phone Records

(6 Pages)

Provided On: November 16, 2024

Tracking ID: 5352251

RE: 7738174398

Case No: HWY24MH013

All times below are reflected in Coordinated Universal Time (UTC) and the equivalent to: 08/05/2024 04:01 - 08/15/2024 16:00 UTC

Date	Time	Duration	Call Type	Direction	Calling Number	Dialed Number	Called Number	Destination Number	IMSI	IMEI	Completion Code	Service Code	Switch Name
2024-08-05	05:01:42	15	moc	Outgoing	[redacted]						Completed Successfully		ELTAS404
2024-08-05	09:14:47		SMSC								Completed Successfully		mavsms_ttn04
2024-08-05	10:05:00	18	mtc	Incoming							Completed Successfully		ELTAS404
2024-08-05	10:51:36	4	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-05	12:11:30		RCS-IM	Outgoing							Completed Successfully		PLRCS403
2024-08-05	12:11:33		RCS-IM	Outgoing							Completed Successfully		PLRCS403
2024-08-05	12:14:37		RCS-IM	Outgoing							Completed Successfully		PLRCS403
2024-08-05	15:44:31	643	mtc	Incoming							Completed Successfully		ELTAS404
2024-08-05	16:27:21	20	mtc	Incoming							Completed Successfully		ELTAS404
2024-08-05	16:48:55		SMSC								Completed Successfully		mavsms_ttmco401
2024-08-05	17:52:23	43	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-06	05:16:52		moc	Outgoing							Completed Successfully		ELTAS404
2024-08-06	05:17:12	9	mtc	Incoming							Completed Successfully		ELTAS404
2024-08-06	08:50:27		SMSC								Completed Successfully		mavsms_pol02
2024-08-06	08:50:55		SMSC								Completed Successfully		mavsms_pol01
2024-08-06	10:29:39		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:30:31		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:30:58		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:31:31		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:32:02		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:32:20		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:32:33		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:32:47		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	10:35:17		SMSC								Completed Successfully		mavsms_plmco401
2024-08-06	13:45:37		SMSC								Completed Successfully		mavsms_ttmco401
2024-08-06	14:20:43		SMSC								Completed Successfully		mavsms_ttn01
2024-08-06	14:21:25	71	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-06	14:21:45		SMSC								Completed Successfully		mavsms_ttmco401
2024-08-06	14:22:50	31	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-06	14:23:47		SMSC								Completed Successfully		mavsms_ttmco401
2024-08-06	14:24:31		SMSC								Completed Successfully		mavsms_ttn06
2024-08-06	14:26:45		SMSC								Completed Successfully		mavsms_pol05
2024-08-06	14:27:02		SMSC								Completed Successfully		mavsms_ttn02
2024-08-06	16:33:47	57	mtc	Incoming							Completed Successfully		ELTAS404
2024-08-06	16:49:00	11	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-06	17:51:15	9	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-07	00:31:03	238	mtc	Incoming							Completed Successfully		ELTAS404
2024-08-07	05:04:29	9	moc	Outgoing							Completed Successfully		ELTAS404
2024-08-07	09:29:43		SMSC								Completed Successfully		mavsms_ttn05
2024-08-07	11:22:11		SMSC								Completed Successfully		mavsms_pol05

2024-08-07	14:13:18		SMSC		[redacted]	Completed Successfully		mavsms_pol04
2024-08-07	14:38:43		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	14:38:44		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	14:50:03		SMSC			Completed Successfully		mavsms_ttn01
2024-08-07	15:00:53		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	15:47:47	127	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-07	16:04:54		RCS-IM	Outgoing		Completed Successfully		PLRCS403
2024-08-07	16:04:54		RCS-IM	Outgoing		Completed Successfully		RMSDAL03
2024-08-07	16:32:28		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	16:51:12	21	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	17:08:06		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	17:09:52		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	17:09:53		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	17:28:26		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	17:41:15	27	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	18:56:53	25	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	18:57:22	149	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	19:00:59	107	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	19:01:52	51	mtc	Incoming		Completed Successfully	041;29;11;12	ELTAS404
2024-08-07	19:01:53	51	moc	Outgoing		Completed Successfully	029;12	ELTAS404
2024-08-07	19:03:48		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	19:23:52		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-07	19:46:32	174	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	19:49:45	265	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	19:55:12	139	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	19:59:18	123	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	20:03:00	21	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-07	20:42:58	15	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-08	04:54:54		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-08	08:35:37		SMSC			Completed Successfully		mavsms_ttn06
2024-08-08	15:18:46	37	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-08	15:54:11		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-08	15:54:12		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-08	16:10:31		SMSC			Completed Successfully		mavsms_ttn06
2024-08-08	16:13:16		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-08	16:44:20	137	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-08	17:08:37	142	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-08	17:41:23	66	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-08	18:02:28	980	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-08	18:09:10		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-08	18:23:14	210	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-08	22:01:09	29	mtc	Incoming		Completed Successfully		ELTAS404
2024-08-08	22:02:52		SMSC			Completed Successfully		mavsms_ttn01
2024-08-08	22:03:09		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-08	22:04:12		SMSC			Completed Successfully		mavsms_ttmco401
2024-08-09	05:08:05	7	moc	Outgoing		Completed Successfully		ELTAS404
2024-08-09	09:16:34		SMSC			Completed Successfully		mavsms_pol03
2024-08-09	14:25:21		SMSC			Completed Successfully		mavsms_pol04
2024-08-09	16:43:13	438	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-09	19:06:05	15	mtc	Incoming		Completed Successfully	029	MLTAS402

2024-08-09	19:06:14	15	moc	Outgoing	[redacted]	Completed Successfully	029	MLTAS402
2024-08-09	20:13:12	15	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-09	20:55:25	45	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-09	23:09:18		moc	Outgoing		Abnormal Completion		MLTAS402
2024-08-10	00:15:38		moc	Outgoing		Abnormal Completion		MLTAS402
2024-08-10	00:15:51		SMSC			Completed Successfully		mavsms_pol05
2024-08-10	01:45:53	12	mtc	Incoming		Completed Successfully	029	MLTAS402
2024-08-10	01:46:01	12	moc	Outgoing		Completed Successfully	029	MLTAS402
2024-08-10	01:47:33		SMSC			Completed Successfully		mavsms_ttn06
2024-08-10	01:47:46		SMSC			Completed Successfully		mavsms_pol02
2024-08-10	01:48:23		SMSC			Completed Successfully		mavsms_ttn01
2024-08-10	01:48:58		SMSC			Completed Successfully		mavsms_pol02
2024-08-10	06:03:34	78	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-10	14:59:19	41	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-10	15:41:31		moc	Outgoing		Abnormal Completion		MLTAS402
2024-08-10	15:41:44	73	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-10	16:12:56	81	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-10	16:14:28	37	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-10	16:15:20	112	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-10	16:51:16	20	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-10	16:53:21	15	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-10	17:42:26		SMSC			Completed Successfully		mavsms_plmco401
2024-08-10	19:13:07	9	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-10	23:36:35		RCS-IM	Outgoing		Completed Successfully		TTRCS403
2024-08-10	23:36:38		RCS-IM	Outgoing		Completed Successfully		TTRCS403
2024-08-10	23:39:42		RCS-IM	Outgoing		Completed Successfully		TTRCS403
2024-08-10	23:39:43		RCS-IM	Outgoing		Completed Successfully		TTRCS403
2024-08-10	23:58:21		RCS-IM	Outgoing		Completed Successfully		TTRCS403
2024-08-12	04:00:43		SMSC			Completed Successfully		mavsms_pol04
2024-08-12	04:00:43		SMSC			Completed Successfully		mavsms_pol04
2024-08-12	04:00:44		SMSC			Completed Successfully		mavsms_pol04
2024-08-12	05:04:17	9	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-12	05:56:27		SMSC			Completed Successfully		mavsms_plmco401
2024-08-12	09:17:21		SMSC			Completed Successfully		mavsms_pol05
2024-08-12	15:24:46		SMSC			Completed Successfully		mavsms_plmco401
2024-08-12	16:53:20	6	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-12	16:57:42		SMSC			Completed Successfully		mavsms_ttn05
2024-08-12	17:04:06	93	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-12	17:19:18	71	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-12	21:17:14	1	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-12	21:19:59	1	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-12	21:20:42	22	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-12	21:26:29	95	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-13	04:54:30		SMSC			Completed Successfully		mavsms_plmco401
2024-08-13	05:00:40	14	moc	Outgoing		Completed Successfully		MLTAS402
2024-08-13	09:03:27		SMSC			Completed Successfully		mavsms_pol03
2024-08-13	16:14:14	166	mtc	Incoming		Completed Successfully		MLTAS402
2024-08-13	16:44:46		SMSC			Completed Successfully		mavsms_plmco401
2024-08-13	16:44:47		SMSC			Completed Successfully		mavsms_plmco401
2024-08-13	16:46:19		SMSC			Completed Successfully		mavsms_pol03

2024-08-13	16:46:25		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-13	16:49:38	951	moc	Outgoing	ompleted Successfully		MLTAS402
2024-08-13	17:08:08	182	moc	Outgoing	ompleted Successfully	042	MLTAS402
2024-08-13	17:11:04	6	moc	Outgoing	ompleted Successfully		MLTAS402
2024-08-13	17:11:18	509	moc	Outgoing	ompleted Successfully		MLTAS402
2024-08-13	17:18:52		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-13	20:00:58		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-13	20:02:17		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-13	20:03:05	1	moc	Outgoing	ompleted Successfully		MLTAS402
2024-08-14	05:09:09	3	moc	Outgoing	ompleted Successfully		MLTAS402
2024-08-14	05:09:51		mtc	Incoming	bnormal Completion		MLTAS402
2024-08-14	05:10:34		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	08:31:04		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	08:45:24		SMSC		ompleted Successfully		mavsms_ttn06
2024-08-14	14:22:32		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	16:59:21	33	moc	Outgoing	ompleted Successfully		DETAS402
2024-08-14	17:03:10		moc	Outgoing	bnormal Completion		DETAS402
2024-08-14	17:11:35		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:12:23		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:12:24		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:12:33		RCS-Gr	Incoming	ompleted Successfully		PLRCS401
2024-08-14	17:12:34		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:12:37		RCS-Gr	Outgoing	ompleted Successfully		PLRCS401
2024-08-14	17:12:39		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:12:42		RCS-Gr	Outgoing	ompleted Successfully		PLRCS401
2024-08-14	17:12:42		RCS-Gr	Outgoing	ompleted Successfully		TTRCS401
2024-08-14	17:13:10		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:13:34		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:14:18		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:16:36	150	mtc	Incoming	ompleted Successfully		DETAS402
2024-08-14	17:17:08		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:17:49		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:19:53		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	17:31:09	20	mtc	Incoming	ompleted Successfully		DETAS402
2024-08-14	17:33:35	341	moc	Outgoing	ompleted Successfully		DETAS402
2024-08-14	17:46:15		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	18:01:01	9	moc	Outgoing	ompleted Successfully		DETAS402
2024-08-14	18:31:06		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	18:32:08	14	mtc	Incoming	ompleted Successfully		DETAS402
2024-08-14	21:00:43		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	21:00:44		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-14	22:33:58		SMSC		ompleted Successfully		mavsms_pol06
2024-08-15	05:04:39		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-15	05:04:53		SMSC		ompleted Successfully		mavsms_ttn03
2024-08-15	09:17:44		SMSC		ompleted Successfully		mavsms_pol02
2024-08-15	10:26:23	4	mtc	Incoming	ompleted Successfully	02A	DETAS402
2024-08-15	10:26:54	4	moc	Outgoing	ompleted Successfully	02A	DETAS402
2024-08-15	10:36:33		SMSC		ompleted Successfully		mavsms_plmco401
2024-08-15	10:37:37	3	mtc	Incoming	ompleted Successfully	02A	DETAS402
2024-08-15	10:38:08	3	moc	Outgoing	ompleted Successfully	02A	DETAS402

2024-08-15	10:41:52	5	mtc	Incoming	[redacted]	Completed Successfully	02A	DETAS402
2024-08-15	10:42:23	5	moc	Outgoing		Completed Successfully	02A	DETAS402
2024-08-15	10:45:23	5	mtc	Incoming		Completed Successfully	02A	DETAS402
2024-08-15	10:45:54	5	moc	Outgoing		Completed Successfully	02A	DETAS402
2024-08-15	10:58:12		SMSC			Completed Successfully		mavsms_plmco401
2024-08-15	11:10:12	5	mtc	Incoming		Completed Successfully	02A	DETAS402
2024-08-15	11:10:44	5	moc	Outgoing		Completed Successfully	02A	DETAS402
2024-08-15	11:16:59	5	mtc	Incoming		Completed Successfully	02A	DETAS402
2024-08-15	11:17:31	5	moc	Outgoing		Completed Successfully	02A	DETAS402
2024-08-15	13:04:57	4	mtc	Incoming		Completed Successfully	02A	DETAS402
2024-08-15	13:05:29	4	moc	Outgoing		Completed Successfully	02A	DETAS402