ASTM D 2513 4” IPS SDR 11.5 DUPONT ALDYL ® A PF2306-T0618L21

Approximately 25-feet of pipe was removed South of the cut-out submitted as evidence. The pipe, salmon colored above showed no signs of rock impingement. It did, however, have two squeeze points as depicted. Both squeeze points were inspected and neither had indications of cracks on the exterior of the pipe.