

Figure 97. Torque Sensor Housing (Forward)

Honeywell Report, Figure 97