Photo 1 - Main Bearing Note No Holes in Bearing Half (NTSB)a