

Photo 2 - Main Bearing Note Holes in Bearing Half (NTSB)b