Photo 11. Oil on right stabilizer.