Photo 7: NTSB Digital Photograph. View of the Fluid Drained from the Open Fuel Line Connection at the Right Wing Attach Point Pertaining to the Wingtip Fuel Tank. The Screwdriver Tip Contained Water Finding Paste.