Photo 1 – View of damage to horizontal stabilizer cable (Courtesy of FAA)

Photo 2 – View of damage to the rudder and horizontal stabilizer cables (Courtesy of FAA)

Photo 3 – View of damage to the wing aileron (Courtesy of FAA)