

Aviation Investigation Notification

Location:	Pahrump, NV	**Accident Number:**	WPR21LA021
Date & Time:	October 16, 2020, 10:00 Local	**Registration:**	N500DL
Aircraft:	Robinson R44	**Injuries:**	2 Minor, 1 None
Flight Conducted Under:	Part 91: General aviation - Business		

The NTSB is conducting a Class 4 investigation into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	Robinson	**Registration:**	N500DL
Model/Series:	R44	**Aircraft Category:**	Helicopter
Amateur Built:			
Operator:	Spring Mountain Raceway LLC	**Operating Certificate(s) Held:**	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	**Condition of Light:**	Day
Observation Facility, Elevation:	KDRA,3230 ft msl	**Observation Time:**	09:53 Local
Distance from Accident Site:	28 Nautical Miles	**Temperature/Dew Point:**	22°C /-10°C
Lowest Cloud Condition:	Clear	**Wind Speed/Gusts, Direction:**	15 knots / None, 30°
Lowest Ceiling:		**Visibility:**	10 miles
Altimeter Setting:	30.25 inches Hg	**Type of Flight Plan Filed:**	NONE
Departure Point:	Pahrump, NV	**Destination:**	Pahrump, NV

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	2 Minor	**Aircraft Fire:**	None
Ground Injuries:		**Aircraft Explosion:**	None
Total Injuries:	2 Minor, 1 None	**Latitude, Longitude:**	36.165812,-115.90381

This information is preliminary and subject to change.

Administrative Information

Investigator In Charge (IIC):	Hicks, Michael
Additional Participating Persons:	Carey Atnip; FAA; Las Vegas, NV
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.

This information is preliminary and subject to change.