Aviation Investigation Notification

Location:	Marietta, TX	**Accident Number:**	CEN21LA077
Date & Time:	December 5, 2020, 13:30 Local	**Registration:**	N371MP
Aircraft:	ROBINSON HELICOPTER COMPANY R44 II	**Injuries:**	5 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a Class 4 investigation into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER COMPANY	**Registration:**	N371MP
Model/Series:	R44 II II	**Aircraft Category:**	Helicopter
Amateur Built:			
Operator:	Private Individual	**Operating Certificate(s) Held:**	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	**Condition of Light:**	Day
Observation Facility, Elevation:	KOSA,363 ft msl	**Observation Time:**	13:30 Local
Distance from Accident Site:		**Temperature/Dew Point:**	18°C /0°C
Lowest Cloud Condition:	Clear	**Wind Speed/Gusts, Direction:**	4 knots, 240°
Lowest Ceiling:		**Visibility:**	
Altimeter Setting:	30.17 inches Hg	**Type of Flight Plan Filed:**	NONE
Departure Point:	Marietta, TX	**Destination:**	Texarkana, TX

This information is preliminary and subject to change.

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	4 None	**Aircraft Fire:**	None
Ground Injuries:		**Aircraft Explosion:**	None
Total Injuries:	5 None	**Latitude, Longitude:**	33.194025,-94.526083 (est)

Administrative Information

Investigator In Charge (IIC):	Aguilera, Jason
Additional Participating Persons:	Daniel Montie; FAA FSDO; Irving, TX
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.

This information is preliminary and subject to change.