Aviation Investigation Notification

Location:	Duson, LA	**Accident Number:**	CEN21LA154
Date & Time:	March 9, 2021, 15:39 Local	**Registration:**	N49XB
Aircraft:	ROBINSON HELICOPTER CO R66	**Injuries:**	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a Class 4 investigation into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER CO	**Registration:**	N49XB
Model/Series:	R66	**Aircraft Category:**	Helicopter
Amateur Built:			
Operator:	TRINITY PAUL AIR LLC	**Operating Certificate(s) Held:**	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	**Condition of Light:**	Day
Observation Facility, Elevation:	KLFT,42 ft msl	**Observation Time:**	15:53 Local
Distance from Accident Site:	9 Nautical Miles	**Temperature/Dew Point:**	23°C /9°C
Lowest Cloud Condition:	Clear	**Wind Speed/Gusts, Direction:**	8 knots / 18 knots, 180°
Lowest Ceiling:	None	**Visibility:**	10 miles
Altimeter Setting:	30.31 inches Hg	**Type of Flight Plan Filed:**	NONE
Departure Point:	Gonzales, LA (KREG)	**Destination:**	Duson, LA

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:		**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	30.1328,-92.1375 (est)

This information is preliminary and subject to change.

Administrative Information

Investigator In Charge (IIC):	Folkerts, Michael
Additional Participating Persons:	Richard Hudgins; Flight Standards District Office; Baton Rouge, LA
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.

This information is preliminary and subject to change.