



Aviation Investigation Factual Report

Location: ODESSA, Texas Accident Number: FTW87GA083

Date & Time: March 21, 1987, 16:00 Local Registration: N62462

Aircraft: BELL 47G-3B-1 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Public aircraft

Factual Information

Pilot Information

Certificate:	Private	Age:	42,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	April 25, 1986
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	119 hours (Total, all aircraft), 82 hours (Total, this make and model), 65 hours (Pilot In Command, all aircraft), 34 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELL	Registration:	N62462
Model/Series:	47G-3B-1 47G-3B-1	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3756
Landing Gear Type:	High skid	Seats:	3
Date/Type of Last Inspection:	March 13, 1987 100 hour	Certified Max Gross Wt.:	2950 lbs
Time Since Last Inspection:	15 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-435-25A
Registered Owner:	ECTOR COUNTY TX SHERIFFS DEPT	Rated Power:	250 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 FTW87GA083

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MAF,3003 ft msl	Distance from Accident Site:	11 Nautical Miles
Observation Time:	15:51 Local	Direction from Accident Site:	75°
Lowest Cloud Condition:	Scattered / 4500 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	ODESSA (E02)	Type of Flight Plan Filed:	None
Destination:	ODESSA (E02)	Type of Clearance:	None
Departure Time:	15:15 Local	Type of Airspace:	Airport advisory area

Airport Information

Airport:	ODESSA/SCHLEMEYER E02	Runway Surface Type:	Grass/turf
Airport Elevation:		Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Simulated forced landing;Straight-in

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
oren injurico.	2110110	All of art Damage.	Gabatantiai
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	31.910995,-102.259788(est)

Page 3 of 4 FTW87GA083

Administrative Information

Investigator In Charge (IIC):	Johnson, J	
Additional Participating Persons:	RICHARD F MARTZ; LUBBOCK , TX	
Report Date:	February 6, 1995	
Last Revision Date:		
Investigation Class:	Class	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=22282	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 FTW87GA083