



Location: Washington, WI Accident Number: CEN21LA021

Date & Time: October 18, 2020, 14:00 Local Registration: N31136

Aircraft: Robinson Helicopter Company R44 Injuries: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make: Robinson Helicopter Registration: N31136

Company

Model/Series: R44 II Aircraft Category: Helicopter

Amateur Built:

Operator: On file Operating Certificate(s) None

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	2P2,652 ft msl	Observation Time:	13:55 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	5.6°C /-2.2°C
Lowest Cloud Condition:	Scattered / 3800 ft AGL	Wind Speed/Gusts, Direction:	9 knots / 14 knots, 290°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	30.07 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Washington, WI	Destination:	Ephraim, WI (3D2)

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	45.389097,-86.924557 (est)

Administrative Information

Investigator In Charge (IIC): Hodges, Michael

Additional Participating Persons: Todd Davis; FAA Milwaukee FSDO; Milwaukee, WI

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN21LA021