



# Aviation Investigation Notification

<b>Location:</b>	Pahrump, NV	<b>Accident Number:</b>	WPR21LA021
<b>Date &amp; Time:</b>	October 16, 2020, 10:00 Local	<b>Registration:</b>	N500DL
<b>Aircraft:</b>	Robinson R44	<b>Injuries:</b>	2 Minor, 1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Business		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Robinson	<b>Registration:</b>	N500DL
<b>Model/Series:</b>	R44	<b>Aircraft Category:</b>	Helicopter
<b>Amateur Built:</b>			
<b>Operator:</b>	Spring Mountain Raceway LLC	<b>Operating Certificate(s) Held:</b>	None
<b>Operator Designator Code:</b>			

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	VMC	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KDRA,3230 ft msl	<b>Observation Time:</b>	09:53 Local
<b>Distance from Accident Site:</b>	28 Nautical Miles	<b>Temperature/Dew Point:</b>	22°C /-10°C
<b>Lowest Cloud Condition:</b>	Clear	<b>Wind Speed/Gusts, Direction:</b>	15 knots / , 30°
<b>Lowest Ceiling:</b>		<b>Visibility:</b>	10 miles
<b>Altimeter Setting:</b>	30.25 inches Hg	<b>Type of Flight Plan Filed:</b>	None
<b>Departure Point:</b>	Pahrump, NV	<b>Destination:</b>	Pahrump, NV

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	2 Minor	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Minor, 1 None	<b>Latitude, Longitude:</b>	36.165812,-115.90381

## Administrative Information

---

<b>Investigator In Charge (IIC):</b>	Hicks, Michael
<b>Additional Participating Persons:</b>	Carey Atnip; FAA; Las Vegas, NV
<b>Investigation Class:</b>	<a href="#">Class 4</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.